

This index has been divided into two parts, an **index of persons** (which includes professional partnerships) and a **general index**. Volume numbers are indicated by **bold** figures. Titles of articles are indicated by inverted commas, of books and journals by italics. A reference in the form '5 24-30' indicates a continuous reference to the subject of the entry; '5 24, 25' or '5 24-30 *passim*' indicates separate references on each page shown. References which include or consist of illustrations are indicated with an 'i' after the page number, except in Volume 1, where illustrations are referred to by their figure number preceded by an 'f'. In the index of persons, a few corrections of names in the text and additions of first names or initials have

been made in order to assist the user; only the more significant errors are noted as such.

In **Volume 1** references are to the pages or figures in the reprint of 1979; the original printing was unpaginated with a large number of blank pages which were eliminated in the reprint, but the figure numbers are the same. For the original version of Volume 1 page numbers should be read as follows:

- 3-7 'Conservation and the architect';
- 8-38 'Structural carpentry in the medieval house' (text, 8-15);
- 39-48 'Sixteenth-century terra-cotta in East Anglia' (text, 39-43).

## INDEX OF PERSONS

Aasen, Hans 10 20, 21  
 Acworth, Angus 10 49  
 Adam brothers 6 41, 43, 7 49  
 Adam, James 6 25  
 Adam, Robert 4 4, 6 28, 31, 9 42, 10 25  
 Adams, Bill 2 37  
 Adamson, David 4 4  
 Adamson, Sally, reports 9 63-6  
 Ahrends Burton & Koralek 6 39  
 Airs, M 8 6, 8  
 Alderton, David, talk 8 55-6  
 Allen, J 7 23  
 Allen, Ralph 5 45  
 Andrew, Martin 10 24  
 Andrew Renton Associates 2 35, 36  
 Andrews, Francis 6 39  
 Anguelova, Mme Rachelle 10 21  
 Archdale, Nicholas 6 41  
 Archer, Peter 7 65  
 Archer, Thomas 10 55  
 Arkwright, Sir Richard 5 40, 41  
 Arnold, Lesley 4 9  
 Artari 9 62  
 Ashbee, C R 7 23, 10 48  
 Ashburton, Alexander Baring, 1st Lord 8 57  
 Ashburton, 5th Lord 8 57  
 Ashby, Ian, report 6 60  
 Ashdown, John, report by 9 66-7  
 Ashurst, John 6 54, 10 51  
 Ashwell, Bernard 4 14  
 Austin, James 2 9

Baggs, A P 1 41, 43  
 Bailey, Douglas 2 35  
 Bailey, F A 6 17  
 Bailey, T A: 'Fluate, some observations' 4 48-9  
 Baines, Frank 9 71, 10 50  
 Baker, Sir Benjamin 5 21  
 Baker, Mrs Eve 4 38  
 Baker, Sir Herbert 9 8  
 Baker, Professor Robert W 2 4-5, 43, 4 8, 35, 42, 44, 5 47, 10 3, 14  
 Baldwin Brown, G, on meaning of 'monument' 9 28  
 Balfour, Max 7 23  
 Ball, Edward 10 61  
 Bankes, Ralph 9 23, 10 9  
 Bankes, Sir Ralph 9 23  
 Bankes, William John 9 24, 10 9  
 Bare, Leaning & Bare 4 43, 10 10  
 Baring, Alexander *see* Ashburton  
 Baring, John 8 58  
 Barker, Ashley 7 16-17  
 Barker, Philip 3 12  
 Barley, M W 8 6  
 Barlow, W H & F Ordish 6 60  
 Barnes, Simon 8 60  
 Barnfield, Keith 7 63

Barrow, Charles 6 17  
 Barry, Sir Charles 9 24, 10 9-15 *passim*  
 Barry, Charles Junr 6 4, 28  
 Batey, Mavis 9 72  
 Batlinger *see* Böttinger  
 Batoni, Pompeo 9 31  
 Bax, E Goodson 7 19  
 Bazago, Louis 4 4  
 Beacon, John 7 3  
 Beard, Roy 3 35, 38-41 *passim*; introduction to Shrewsbury study tour 3 34; talk 3 36  
 Beart, Robert 4 47  
 Beaty-Pownall, Inger, report 6 57  
 Beckett, Sir Edmund (Lord Grimthorpe) 8 49; on church restoration 7 6  
 Bedingfield, Edmund 1 42  
 Beit, Sir Alfred and Lady 6 44  
 Bell, Paul, report 6 49-50  
 Bell, Thomas 4 10, 11, 12  
 Bendlowes, William 1 10  
 Benedict, Abbot 1 9  
 Bennett, Corinne *see* Wilson, Corinne  
 Bennett, Keith, report 8 57-8  
 Benson, Jeremy 9 72  
 Bentley, Alf 5 44  
 Bernasconi, Francis 4 4  
 Berrecci, Bartolomeo 10 46, 47  
 Berwick, 1st Lord 3 34  
 Berwick, 3rd Lord 3 35  
 Berwick, Lady 3 35  
 Biddulph family (plasterers) 10 59  
 Bidwell, T G 8 15; 'The restoration and protection of structural and decorative cast iron at Covent Garden Market' 5 24-30i  
 Biek, Leo: 'VISAR: Conference April 27th 1984' 8 28-32i  
 Bindon, Viscount 8 58  
 Birkett, Jenny, report 3 45-6  
 Biro, Tibor 7 24  
 Bisgrove, Richard 9 73  
 Bishop, Christopher 7 63  
 Blacklay, Anthony 2 36  
 Blair, Major 4 38  
 Blanchard, H N 6 3, 4  
 Blomfield, A W 10 60  
 Blomfield, Sir Reginald 1 42, 9 71  
 Blore, Edward, 6 27  
 Böttinger, Herr 9 46, 61, (*in error* Batlinger) 62  
 Boulton, Matthew 4 4  
 Bourgeois, Sir Peter Francis 6 33  
 Bourne, Miss Patricia 6 58  
 Boutwood, James, talk 9 25-7  
 Bowe, Patrick 6 43-4  
 Bowyer, Peter, report 9 61-3  
 Boyle, Richard *see* Burlington  
 Brain, David 4 40, 41, 42; report 4 10-13  
 Brain, R G 7 3  
 Brent, Edward 8 26, 27  
 Brettingham, Matthew (*recte* Robert Furze Brettingham) 10 9, 15  
 Brindley, James 5 42

Bristow, Ian C 6 49, 9 33, 35, 66, 10 58; 'Proposed [Scottish] conservation centres' 2 39-41; 'Two exterior treatments used to imitate stone during the eighteenth and early nineteenth centuries' 4 3-6i; 'Repainting eighteenth-century interiors' 6 25-333; 'The redecoration of the Dulwich Picture Gallery 1980-81' 6 33-6i; 'The Great Drawing Room from Bowood' 10 25-36i; reports: Rome 1975 2 17, Glasgow 1976 2 34-5, Attingham 1977 3 34-5, Marburg and North Hessen 1984 9 67-8  
 Bristow, Ian C and J Redmill: 'The Casino at Marino, Dublin' 9 29-44i  
 Brock, Patricia, report 7 57-8  
 Brockett, Peter 8 19  
 Brohl, Elmar, talk 9 59-60  
 Brown, C H 6 17  
 Brown, G Baldwin, on meaning of 'monument' 9 28  
 Brown, Lancelot ('Capability') 5 42, 6 44, 10 55  
 Brown, Sidney 2 29, 4 40  
 Brown, Stuart 2 35, 36  
 Brown, Trevor 5 17  
 Brunel 9 11; Marc 8 53, 54  
 Buckler, John 6 27  
 Buggiey, F R 10 49  
 Bunker, John 3 39, 40  
 Burchnall, Yvette, drawing 6 20  
 Burgh, Thomas 6 39  
 Burke, Edmund 4 5  
 Burlington, 2nd Earl of 7 53  
 Burlington, Richard Boyle, 3rd Earl of 9 29  
 Burman, Peter 9 67; 'Conservation and recording: the Church's contribution' 7 9-11; 'Conservation in Poland' 10 37-47i; report 9 53-5  
 Burn, William 7 31  
 Burton, Decimus 6 38, 9 4  
 Buttress, Donald, report 3 32-3

Cadell, W 2 33  
 Caley, Major 10 15  
 Calvocoressi, Paul, reports: Bruges 1977 3 29-31, Shrewsbury 1977 3 38-9, Wells Cathedral 1979 4 35-6, Ashbourne 1980 5 36-8, Dublin 1981 6 38-40, lead-glazing works, Norwich 1982 7 58-9, Marburg and North Hessen 1984 9 55-8, Ironbridge 1985 10 59-60  
 Cant, Ronald 2 31  
 Cantwell, Wilfrid 6 40  
 Carbone, Maurice 7 15  
 Caroe, Alban D R 2 22, 23, 26, 4 35  
 Caroe, Martin 2 42, 44, 4 37, 7 16, 41, 8 60, 9 24; 'Repairs to Vicars' Chapel, Wells' 4 7-9; 'Wells Cathedral, the West Front: policy and techniques' 4 43-4; 'Architectural recording: the architect's dilemma' 7 13-14; 'Kingston Lacy, Dorset: an architectural case history' 10 9-15i  
 Caroe, M B and A D R Caroe: 'Wells Cathedral: the West Front conservation programme' 2 3-10  
 Caroe & Martin 7 41, 9 24, 10 9  
 Carr, John 6 30

- Carter, Alan 8 5, 14  
 Carus, Charles, report 9 24-5  
 Cassels *see* Castle  
 Castle/Cassels, Richard 6 40, 42, 44, 48  
 Caulfield family 9 30-1  
 Caulfield, James *see* Charlemont  
 Chambers, Sir William 4 3, 4, 6 27, 28, 31, 39, 43, 49, 9 29, 31, 32, 33, 35, 38, 40, 41, 42, 44  
 Charlemont, James Caulfield, 1st Earl of 9 29-35 *passim*, 37, 40, 41  
 Charles, F W B 3 37, 38, 40, 41, 6 57, 58; 'The timber-frame tradition and its preservation' 3 5-28; SPAB comment on his article 5 49; his reply to SPAB 5 49; 'Contrasts in the conservation of timber buildings' 9 18-21; 'The conservation of timber buildings: ICOMOS Wood Committee meetings in Japan, Norway and Bulgaria' 10 16-23; lecture on repair of historic timber structures 1977 3 38  
 Chitham, Robert 7 21n  
 Christie, Håkon 9 20, 10 18, 19  
 Clark, Harold 6 41  
 Clarke, Sir Ashley 4 22; and Lady 4 18, 19  
 Clarke, Somers 9 11, 12  
 Clayton, George 5 45, 47  
 Cleminson, Antony 9 24, 10 14, 15  
 Clifton Taylor, Alec 2 12, 8 19  
 Clough, Ronald 10 10, 14  
 Coad, Jonathan 8 52, 55  
 Cockerell, C R 8 57, 9 11  
 Colchester, Linzee 2 9, 26, 27  
 Cole, Domenic 10 55  
 Coles, Michael, report 7 65  
 Collet, Pierre 9 42  
 Collins, Sam 5 51  
 Colson, John 2 43  
 Comely, C Basil 4 13  
 Conolly, Thomas 6 44  
 Conolly, William 6 44  
 Conradi, Herr 9 46, 66, 67  
 Constandt, Mr 3 33  
 Cooper, Nicholas 7 16, 8 59; 'The Royal Commission on Historical Monuments (England) and the National Monuments Record' 7 11-13  
 Cossons, Neil 3 37, 5 20  
 Costello, John 6 49  
 Crabtree, Cherry 4 35  
 Cragg, Thomas 6 19  
 Cramb, Albert 2 38  
 Crawford, Ian, report 10 54-6i  
 Crayford, Robert: 'Plain-tiled roofs: a guide to post Great Fire and early 18th-century practice, Part I' 2 11-14; 'Notes on the Use of Trass in the Wren period' 5 11-14 (referred to 6 23); 'Fluctuations in the price of lime in the period 1672-1711' 8 25-7  
 Crease, James 4 4  
 Crockett, J 8 34  
 Cudworth, C L 8 3, 8, 10-13 *passim*, 19  
 Cunliffe, Michael and Jocelyn, report 4 33-4i  
 Curry, Ian, reports 2 19, 3 36  
 Curtis Green, W 2 45
- Daifuku, Hiroshi** 10 16, 17  
 Dale, Antony 10 24  
 Dallas, R W A 8 60, 61  
 Dallas, R W A and John Fidler: 'Seminar on setting standards for photogrammetric surveys' 1984 8 59-61  
 Dalton, Ruth 10 49  
 d'Amboise, Georges, Cardinal Archbishop of Rouen 1 42  
 Dance, George the Elder 8 33, 35  
 Dance, George the Younger 4 4, 40, 8 33, 34  
 Danışman, Günhan 2 2; report 2 15-16, 30-2  
 Darby, Abraham 1 3 36, 10  
 Darby, Keith 8 15, 16, 18, 20; reports 7 61-2, 64-5, 8 55-7  
 Darley, Henry 6 38  
 Davey, Norman 5 11, 12, 13  
 Davies, D Richard 10 55: 'The management of guardianship monuments' 10 49-53  
 Davies, Margaret 10 54, 57  
 d'Aviler, A C 9 42  
 Davis, Major C E 10 3, 4  
 Deane & Woodward 6 39  
 de Beaumont, Guyot 8 4  
 de Grey *see* Grey  
 de Haveus, Theodore 8 6  
 de Keyser, Hendrick 8 8  
 de Kretser, Shiela, reports 7 60-1, 9 23-4  
 Delabrière 3 35  
 Dellow, Christopher 10 60-1  
 Deltchev, George 10 21  
 Deneux, Henri 1 11  
 Desenfans, Mr and Mrs Noel 6 33  
 Desimpelaere, Werner 3 31  
 de Vries, Jan Vredeman 8 5
- Dientzenhofer 9 62  
 Dobson, John 9 46, 63  
 Dodwell, C R 5 13  
 Doria, Barnardo Rossi 2 16  
 Douglas, William 7 49  
 Dowrick, David 2 42  
 Drake, Norman 4 41  
 Drewett, Peter 9 73  
 Drummond, Henry 8 57  
 Drury, Paul 10 52  
 Dugardyn, Luc 3 31  
 Dunphy, T Austin 9 34  
 Dykes Bower, Stephen 2 27, 3 42
- Earl, John** 5 52; 'Measured drawing: The 'Survey of London' tradition' 7 19-26i  
 Earle, Sir Lionel 9 71  
 Eastlake, C 6 4  
 Eccles, Sir John 6 41  
 Eckersall, Nixon 2 22  
 Eckingham, Sir Robert 1 43  
 Eden, W A 5 51  
 Edge, Roy 7 63  
 Edwards, Jack 9 12  
 Elbert, Wolfdietch 4 21  
 Elliott, James 4 45; reports: Martock 1975 2 22-3; Wells 1975 2 23, 26-8; Bath 1975 2 29; Winchester 1976 2 42-4; Much Wenlock 1977 3 38; lecture by F W B Charles 1977 3 38; Salisbury Cathedral 1978 3 44-5; Bath 1979 4 40; Cheltenham 1981 7 63-4  
 Ellis, Reg: 'Shaped Gables in Norfolk and Suffolk 1570 to 1741' 8 3-20i  
 Ellis, Richard 8 52  
 Elson, Paddy, report 6 50  
 Emerton, Alexander 4 3  
 Epstein, Jacob 5 47  
 Esser, Professor 4 18  
 Evans, Douglas: 'Historic landscapes, parks and gardens: a short course on their protection and conservation' July 1985 9 72-3  
 Evans, Frank A 5 51, 7 24  
 Evans, Roger W: 'The Buckinghamshire lists' 10 23-4; reports 4 38-9, 9 58-60  
 Evans, William 4 4
- Fagan, Alan** 7 26  
 Farington, Joseph 6 33, 34  
 Farthing, Cecil 7 28  
 Faulkner, Keith 7 29  
 Faulkner, Patrick 8 17, 10 52  
 Fawcett, Edward 9 72, 73  
 Fawcett, Jane 4 19, 9 72; 'Greater churches: damage by visitors' 9 6-10; introduction to Venice study tour 1978 4 15  
 Feilden, Sir Bernard 1 7, 8 25, 9 18, 10 16; talk 7 64-5  
 Fernie, Eric: 'The visual interpretation and analysis of medieval cathedrals' 8 21-5i  
 Ferrers, Elisha 1 43  
 Ferrey, Benjamin 2 23, 26, 27, 4 43  
 Fidler, John 8 59, 61, 9 21; 'Non-destructive surveying techniques for the analysis of historic buildings' 5 3-10i; 'The conservation of architectural terracotta and faience' 6 3-16i; 'Structural repairs to the Long Parlour floor in the Mansion House in the City of London' 8 33-43i; talk on non-destructive testing of materials 7 66-8; talk on conservation in the USSR 9 21-3  
 Fidler, John & R W A Dallas: 'Seminar on setting standards for photogrammetric surveys' 1984 8 59-61  
 Findlay, Donald 7 10  
 Fisher, Alfred 7 65  
 Flenley, Richard 10 55  
 Fletcher, Colonel 6 4  
 Floris, Cornelis 8 5  
 Foramitti, Dr Hans 7 15  
 Forbes, John 7 63  
 Foscari, Antonio & Barbara 4 26  
 Foster (*recte* Frost), Alan and Janet, report 4 25-6  
 Foster, Peter 3 42, 6 58, 59, 7 16, 9 9  
 Fowler, Angus 9 50, 51, 54, 58, 68; 'The Förderkreis alte Kirchen' 9 47-50; introduction to Marburg and North Hessen study tour 1984 9 45-47  
 Fowler, Charles 5 24, 25  
 Fowler, Daryl 8 60  
 Fowler, John 6 28  
 France, Roger: 'Aspects of conservation practice in France' 7 42-7i  
 Francini brothers 6 40  
 Freeman, Robin 2 42  
 Frost *see* Foster  
 Funssen (*recte* Janssen), Peter 9 59
- Gabriel, Ange-Jacques** 9 29  
 Galilei, Alessandro 6 44
- Gallet, Michel 9 42  
 Gameren, Tilman van 10 47  
 Gandon, James 6 42, 43, 46  
 Garbutt, Matt 7 23  
 Gaunt, S and R Potter: 'Electronic structural monitoring: experiences at St Paul's and Chichester Cathedrals' 9 11-18i  
 Geddes, Jane 8 57; 'Medieval decorative ironwork' 6 56-7  
 Gem, Richard 7 16  
 George, Ernest 10 2  
 Gett, Harry 10 21  
 Gibbs, James 8 33, 61, 10 55  
 Gifford & Partners 3 44, 6 52, 9 11  
 Gilbert, Alfred 10 58  
 Gilman, Michael, report 8 58-9  
 Gjaerder, Per 10 20  
 Glass, Alasdair, reports 3 42-3, 6 58-9  
 Glass, Alasdair and P Bowyer, report 9 61-3  
 Godfrey, Walter Emil 7 28; obituary 6 24; report 4 36  
 Godman, Ernest 7 23  
 Goldsworthy, Tony 5 47  
 Goodall, Rodney 4 40; report 2 28-9  
 Goodhart-Rendel, H S, index 7 29  
 Goodsby, John 8 52  
 Goodson, E Bax 7 19  
 Goscombe John, W 10 58  
 Gosney, Roy, report 5 38-40  
 Gowans, James 7 52  
 Grafton, Duke of 4 40  
 Grainger, John, report 4 39-40  
 Greenwood, Cedric 6 18  
 Gregory/Gregory Thain 5 45, 46, 47  
 Gregory, William 8 26, 27  
 Green, John, talk 7 61-2  
 Grey, Henry *see* Kent  
 Grey, Jemima, Marchioness 10 55  
 Grey, Philip Weddell, Earl de 10 54, 55, 56  
 Griffin, Ernest 5 45  
 Grimthorpe, Lord *see* Beckett  
 Grogan, Arthur H 5 51, 7 20, 24  
 Grove-White, Robin 9 72  
 Guggenheim, Mrs Peggy 4 16  
 Gunn, Edwin 6 24  
 Gunther, R T 9 23  
 Gwilt, Joseph 6 23, 8 49, 50  
 Gwynne, John 3 39
- Hamilton, Jean** 9 43  
 Hardwicke, Philip Yorke, 2nd Earl of 10 55  
 Hardy, John 9 38  
 Hardy, Thomas, on ancient cottages 7 69  
 Hare, Richard 3 29; report 7 62  
 Harris, John 10 35  
 Harris, Roger: 'A survey of medieval repairs to the fabric of the West Front, Wells Cathedral' 7 7-8i  
 Harrison, Norman 5 51  
 Harwood, Francis 9 33  
 Hauduroy, Nicholas 10 55  
 Haussmann, Baron 6 17  
 Hawkes, Pamela 6 22  
 Hawthorne, Nathaniel 6 17  
 Hayes, Mr 4 8, 9  
 Hayson, Mr 8 58  
 Healey, F H 7 20  
 Healey, Tim 5 52  
 Heath, Bob: 'Quarrying in northern England: study tours 1981 and 1982' 7 52-4  
 Hempel, Kenneth 2 26, 4 30, 31  
 Hendry, Professor A W 2 40; lecture on stability of walls 2 37-8  
 Henley, Sir Robert 8 57, 58  
 Herbert, Tony 10 60, 61  
 Heseltine, Michael 10 24  
 Hewett, Cecil 2 26, 43, 9 25-6; 'Structural carpentry in the medieval house' 1 8-38i  
 Heyman, Professor 2 26  
 Heysham, Terence 10 25, 28  
 Hitchcock, Henry-Russell 8 4, 5, 8  
 Hodges, Desmond 2 32  
 Hodgson, Richard, report 3 41  
 Hoile, Charles, report 5 43-4  
 Holl, Edward 8 53  
 Holland, Henry 4 4, 5  
 Honeybourne, David: 'Harmful interactions between building materials' 8 44-8i  
 Hooke, Robert 8 43  
 Horioka, Kunisuki 9 21  
 Horn, Walter 6 57  
 Howard, Mr 2 21  
 Howard, Ebenezer 6 18  
 Hugh Roberts, Graham & Stollar 4 41  
 Hughes, Philip 10 23  
 Hughes, Vernon 5 53; 'Cupolas and characters' 5 51-2  
 Hume, Sir Alan 2 33  
 Hume, Ian: 'The Iron Bridge, Shropshire: repainting and repairs 1980' 5 20-3i

INDEX TO VOLUMES 1-10

- Hunter, Dougal 6 55; 'Bath Stone in building: its use, repair and conservation', report of discussion 5 45-8i  
 Hussey, Christopher 4 4  
 Hutton, Mr 5 52  
 Hyvert, G 3 32
- Insall, Donald** 8 17; 'A current problem: 'brashness' in the timber of a wooden ceiling' 7 55-6i  
 Irvine, James Thomas 6 23n, 7 3, 10 4  
 Ison, Walter 5 51
- Jack Bill Murray** 3 32  
 Jackson, Sir Thomas 2 42  
 Jacques, David 9 73  
 James, Mr 2 27  
 James, John 8 33  
 Janney/Jannys/Jenn(ey) family 1 40, 41  
 Jannys, Robert 1 43  
 Janssen *see* Funssen  
 Jebb, Philip 2 29  
 Jefferies, Jeremy 7 63  
 Jeffries, Colin, report 7 61  
 Jenkins, Mr and Mrs 2 28  
 John, W Goscombe 10 58  
 Johnson, P 8 59  
 Johnston (Johnson), Francis 6 41, 42, 46, 48, 49  
 Jones, Alfred 9 38  
 Jones, Inigo 2 43, 10 50  
 Joyce, Barry 5 38
- Kaley, Diana** 4 22; talk on the role of private committees in the restoration of Venice 1978 4 19-21  
 Kamen, Ruth, *British and Irish Architectural History, A bibliographical guide to sources of information* 7 35  
 Keene, Henry 6 39, 10 25  
 Kelly, Francis, report 9 52-3  
 Kelly, John 6 42  
 Kelsall, Frank: 'Listing and the London County Council' 10 48-9; report 3 40-1  
 Kent, Henry Grey, Duke of 10 55  
 Kent, William (architect) 6 28, 10 55  
 Kent, William (supplier of lime) 8 26  
 Kenyon, Mark 9 24, 25  
 Kersting, A F 7 33  
 Kessler 4 49  
 King, Michael: 'The restoration and repair of cast-iron and glass verandahs in Lord Street, Southport' 6 17-23i  
 Kinward, Thomas 8 43  
 Kip, J 10 55  
 Knight, David 3 39, 40  
 Knowles, George, reports: Gloucester 1978 4 13-14, Venice 1978 4 16-17, 21-5i, 30, 34, Dublin 1981 6 40-1, Marburg 1984 9 50-1  
 Koralek, Paul 6 39  
 Kramer, Herr 9 62
- Lacey, Charmian**, talk on conservation in the USSR 9 21, 23  
 Landsberg, A C (Bertie) 4 25, 26  
 Lane, Geoffrey 5 36, 39, 41, 42; introduction to Derbyshire study tour 1980 5 34-5; 'Historic buildings preservation trusts: the Derbyshire experience' 5 35-6; introduction to Shardlow 5 42-3  
 Langley, Batty 2 13, 5 12, 8 26, 27, 33  
 Lansdowne, 1st Marquis of 10 25  
 Laussedat, Aimé 7 15  
 Laxton, W R 4 4  
 Lazzarini, Professor Lorenzo 4 21  
 Leadbetter, Mr 2 33  
 Leask, Dr Harold G 9 34, 40, 41  
 Lees-Milne, James 2 29  
 Lemaire, Professor 3 32  
 Leoni, Giacomo 8 33  
 Lethaby, W R 9 18, 71, 10 23; on whitewashing 5 50  
 Lewis, Elisabeth 7 29  
 Leybourn, William 2 12  
 Leysingham, Robert 4 14  
 Lindsay, Ian 2 36  
 Lindsay, Maurice 2 37  
 Lindsey, Norman 7 9, 8 28, 32; 'Photogrammetry in the conservation programme' 7 15-16  
 Lines, Peter 10 10  
 Lloyd, Nathaniel 2 13, 8 6, 49  
 Lodge, Sir Oliver 5 50  
 Longhena, Baldassare 4 32  
 Lord, Anthony 9 73  
 Lorimer, Sir Robert 2 32  
 Loudon, J C 4 5  
 Louis Napoleon, Prince 6 17  
 Louw, H J 8 43  
 Lubbock, Sir John 10 48, 50  
 Lucan, Patrick Sarsfield, Earl of 6 43
- Lutyens, Sir Edwin 5 52  
 Luynes, Duc de 9 42  
 Lyming, Robert 8 10
- Macartney, Sir Mervyn** 9 12  
 McCullagh, James 6 48  
 Mace, Mr 8 56  
 Macfadyen, Neil: 'Temple Church, London: the Great West Doorway' 9 3-6i; report 3 39-40  
 McHardy, George 7 16  
 Mack, Robert 6 48  
 Mack, Simon, report 10 57  
 Mackenzie, Jean 5 39  
 Mackintosh, C R 2 34  
 McLaughlin, David 6 60, 10 3; 'Observations on trass' 6 23; 'The repair of a cast-iron bridge over the Kennet and Avon Canal, Sydney Gardens, Bath' 5 30-33i; 'Lime-based mortars in Bath' 6 54-6  
 McLaughlin, David and L Tindall: 'The Statue of Bladud in the King's Bath of the Roman baths at Bath' 7 3-5i  
 McNeill, Sir John 6 45  
 McParland, Dr Edward 6 38, 39  
 McWilliam, Colin 2 31  
 Marks, Stephen 4 39; 'The protection of historic buildings in Westminster' 2 45-7; 'Hamilton's, Kilmersdon, Somerset' 4 45-7i; 'Quirked ogee, chamfered: some notes on a common moulding' 8 49-51i; 'Listing in Hessen' 9 69-70; reports 1 17, 9 60-1, 70-1  
 Marks, Tordis 4 39  
 Marney, 1st Lord 1 42  
 Marsden-Smedley, Basil 10 49  
 Marsh, Peter 9 9  
 Marshall, Peter, report 4 32-3  
 Martin, Canon 2 26, 27  
 Martin, David 2 35  
 Martin, Ernest 9 18  
 Martin, Thomas 4 4, 5  
 Mason, William 4 5  
 Mawson, Thomas H 6 18  
 Maxwell, Ingar 2 38  
 Meehan, Brian 6 39  
 Melcombe, Lord 6 28  
 Melli, Piero, report of lecture on pollution in Venice 1978 4 22-3i  
 Meydenbauer, Albrecht 7 15  
 Michell, Gordon 5 38  
 Milinaric, David 6 39  
 Miller, Mr 2 33  
 Mills, Kenneth 5 51  
 Milltown, Lord 6 40  
 Mitchell, Tony 10 14  
 Montague, George 9 32  
 Montanari, Armando, talk 2 17  
 Montsopoulos, Dr N C 10 21  
 Morigi, Dr 4 20  
 Morris, Richard 7 13  
 Morris, William 3 10, 26, 5 49, 9 21  
 Morrison, Allan B, report 5 42-3  
 Mosse, Dr Bartholomew 6 42  
 Mosse, John 5 45, 47  
 Mott, Sir Basil 9 12  
 Mott, Hay & Anderson 5 21  
 Moxon, Joseph 2 13, 8 26  
 Muggleton, Brian, report 6 57-8  
 Myers, Graham 6 39
- Nash, F 9 5**  
 Nash, John 3 34, 35, 4 4, 5, 6 34  
 Naylor, Andrew/Naylor Conservation 10 57-8  
 Neatby, W J 10 60  
 Neve, Richard 2 12, 13, 4 3, 8 26, 27  
 Newman, John 8 8  
 Nicholson, Peter 4 4, 5, 8 49, 50i  
 Nierop-Reading, Vic, report 7 59-60  
 Noble, Geoffrey: 'The role of photographic archives in conservation' 7 27-41; report 6 49  
 Norreys, Thomas 2 9
- O'Connell, Mr and Mrs** 6 42  
 O'Connor, Mrs Consuela 6 39  
 Odgers, D and L Tindall: 'The conservation of Roman rendering at the Roman baths, Bath' 10 3-9i  
 Ogbourne, Sir William 5 52, 7 23  
 Ogston, R M 5 45  
 Ormiston, Linda 10 4  
 Orr, Mr 4 9
- Paine, James** 6 28, 29  
 Palladio, Andrea 4 25-29 *passim*, 32  
 Pancheri, Christopher, report 4 18-19  
 Parke, Robert 6 46  
 Parker, John 9 31  
 Parker, J H 2 27  
 Parker, Vanessa 8 11  
 Payne, Alec 9 12
- Peace, David: 'Traditional clear glass in churches, or, 'Keep the Crown'' 7 17-18; report 4 28  
 Pearce, David, reply to F W B Charles 5 49  
 Pearce, Sir Edward Lovett 6 40, 44, 45, 46  
 Pearson, J L 9 8  
 Pennell, Joseph 7 23  
 Peters, Dr J F C 4 13  
 Peters, Matthew 9 30  
 Peto, Sir Morton 8 56  
 Pevsner, Sir Nikolaus 1 43, 2 26, 5 39, 8 3, 6, 7, 8, 13i, 33, 53  
 Philippot, Professor Paul 2 16-17, 18  
 Phillimore, Claud 4 25-6  
 Phillips, Clara 9 63  
 Pilkington, Sue, report 10 60-1  
 Pitt, Joseph 7 63  
 Pitt-Rivers, General 10 50  
 Pollen, J H 6 48  
 Pollock, Ferrier 6 48  
 Porden, William 6 27  
 Powys, A R 8 49, 9 18, 10 23  
 Pratt, Sir Roger 8 26, 9 23, 10 9-12 *passim*, 14  
 Potter, Margaret and Alexander, *The Building of London* (1945), illustration from 5 53  
 Potter, Robert 9 8  
 Potter, Robert and Stuart Gaunt: 'Electronic structural monitoring: experiences at St Paul's and Chichester Cathedrals' 9 11-18i  
 Price, Dr Clifford 5 46, 47, 8 44, 10 9  
 Price, Uvedale 4 5  
 Prince Regent 8 57  
 Pringle, Lt-Gen Sir Steuart 8 55  
 Pritchard, Thomas 3 34, 39  
 Pugin, A W N 6 4, 7 56, 66  
 Pugin, E W 3 39  
 Purcell, Donovan, 'Sixteenth-century terra-cotta in East Anglia' 1 39-48i  
 Purcell, Mrs Donovan 7 29  
 Purvis, Mrs 2 32
- Quilby/Quilley, Thomas** 7 3  
 Quin, Pat, report by 5 40-1
- Raeburn, Henry** 2 31  
 Read, Christopher 6 60  
 Rebecca, Biagio 6 27  
 Redgrave, Gilbert 6 4  
 Redmill, John 6 39, 48, 49; introduction and postscript to Dublin study tour 6 37-8, 50  
 Redmill, John and Ian Bristow: 'The Casino at Marino, Dublin' 9 29-44i  
 Rennie, John 5 30, 10 59  
 Repton, Humphry 4 6  
 Richardson, Sir Albert 9 27  
 Rickman, Thomas 6 19  
 Rivington 5 11, 12  
 Roberts, Hugh 4 41  
 Rodwell, Dr Warwick 4 9, 35, 36, 7 41  
 Rogers, Richard 10 25  
 Rohrbach, Erwin 9 57  
 Roman, Jacob 8 43  
 Rome, Alan 2-27, 3 44  
 Rossi, Anthony, reports 4 27, 30-1  
 Ruskin, John 6 4, 39  
 Ryder, Roger 5 37, 39  
 Rylands, Philip 4 15-18 *passim*, 25, 28, 32
- St Boniface of Crediton** 9 46, 53, 68  
 St John Hope, W H 4 36  
 Sales, John 9 73  
 Salmon, William 2 13, 8 26  
 Salomon, David 9 63  
 Salzman, L F 7 8  
 Sambrook, John 7 21, 22, 23, 25, 26  
 Sampson, Jerry 7 11  
 Samwell, William 8 57, 58  
 Sandon, Eric 8 6, 7, 8, 14  
 Sandwich, Earl of 8 54  
 Sankey, Col C E P 9 12  
 Sarsfield, Patrick *see* Lucan  
 Sayer, Richard 8 26, 27  
 Scanlan, Pascal 6 40  
 Schäfer, Karl 9 59, 68  
 Scheelinks, W 7 3i  
 Schofield, John 5 48, 6 54  
 Scott, George Gilbert 2 34, 4 6, 7 3, 6, 10, 9 8  
 Sebire, Andrew 5 38  
 Sebire Allsopp 5 38, 41  
 Seddon, J P 9 8  
 Sell, John, report 4 19-21  
 Sellars, Henry 6 18  
 Shabetai, Daniel, report 10 57-9  
 Sharpe, Edmund 6 4  
 Sheaff, Nicholas 6 40, 45  
 Shelburne, 2nd Earl of 10 25  
 Shelburne, Lady 9 33, 34, 43  
 Shelton, Ralph 1 40  
 Sherwin, Nigel 4 40  
 Short, Tony 5 37

- Sickels, Lauren-Brook: 'The development of mortars in Scotland' 7 47-51 (comment on article 8 32)
- Simpson, Archibald 9 46
- Simpson, James 2 30, 39; introduction to Scottish study tour 1976 2 30
- Slade, H Gordon 4 10-13 *passim*
- Slattery, David 6 40
- Smeaton, John 5 11
- Smirke, Robert 8 33, 57
- Smirke, Sydney 9 4
- Smith, Chris, report 7 65-6
- Smith, John 6 39
- Smith, Peter 3 39, 10 21
- Smith, Ron 8 60
- Smith, Stuart 10 59
- Smith, J T 9 26
- Smythson family 8 7
- Smythson, John 8 8
- Smythson, Robert 8 5
- Snowden, R A 2 36, 37, 39
- Soane, John 6 29, 33, 34, 7 63
- Southern, Jeremy 10 60, 61
- Southon, Jean, report 3 35-6
- Spinnage, John 10 33
- Spring, Margaret 1 40
- Spring, Roy 3 44, 45
- Stancliffe, Martin, report 4 28-9
- Stapleton, Michael 6 41, 42, 43, 48
- Steingruber: letter S 6 61i
- Stewart, Ian H 4 15; obituary of W E Godfrey 6 24; reports 2 17-18, 35-7, 3 31-2, 6 46-9
- Stirling, James 2 32
- Stocker, Ann, reports 6 44-6, 9 55
- Stoker, Gordon 8 60
- Stollar, Derek 4 40, 41, 5 45, 47; report 4 40-43
- Stone, Nicholas 8 8
- Stothert, George 5 30, 31
- Stratton, Arthur 6 27
- Stratton, Dr Michael 10 57
- Street, G E 6 47, 9 8
- Strik, Henk 9 24, 10 14
- Strobell, B 10 43
- Stroud, Dorothy 8 33; index 7 29
- Stuart, James 'Athenian' 6 27
- Suger, Abbot 8 23
- Summerson, Sir John 4 4, 5, 40, 7 28, 8 3, 6, 7, 8, 33
- Sumsion 2 5, 6
- Sutton, William 8 26, 27
- Taggart, Imelda 9 45, 46; report 5 41-2
- Takahashi, Masao 10 17
- Tanghe, Professor Jan 3 29-30, 31
- Tasker, John 8 59
- Tatton-Brown, T 7 12
- Taylor, I 4 4
- Taylor, James 6 4
- Taylor, Peter 3 44, 6 52
- Taylor, Robert 8 33
- Telford, Thomas 9 11, 10 59
- Temminck Groll, Professor C L 7 56, 8 6, 8, 14, 17, 18, 19
- Thiene, Clementi 4 23-5
- Thiersch, Dr 9 46, 52, 60, 69
- Thomas Bedford & Partners 2 22
- Thompson, Edward 3 26
- Thornhill, Desmond 5 43
- Thornton, Peter 9 38
- Thorpe family 8 7
- Thorpe, John 8 8
- Thorpe, Thomas 8 7
- Tillemans, Peter 10 55
- Tindall, L and D McLaughlin: 'The statue of Bladud in the King's Bath of the Roman baths at Bath' 7 3-5i
- Tomasin, A, talk 4 33-4i
- Torrignano 1 41, 42
- Troelrsch (*recte* Troeltsch), Herr 9 63
- Tschudi-Madsen, Stephan 9 19, 10 18
- Tuccolo, Giovanni 4 23
- Tudor-Craig, Pamela 2 9
- Turner, Carpenter 2 43, 44
- Unger, Martin 9 63
- Valadier, G 2 17
- van den Abeele, Dris 3 29
- Vanherman, T H 6 34
- Vanvitelli, Luigi 9 31
- Verity, Simon 5 46
- Vierpyle, Simon 9 31-2
- Vincent, Alan 2 22, 10 13
- Viollet-le-Duc, E-E 3 18, 38, 7 42, 44, 45, 9 20, 10 16
- Vitruvius 5 47
- Vivian, John 4 40
- von Helge, Wolf 2 20
- Walker, Andrew, report 4 17-18i
- Walker, F H 6 40
- Wallach, Lewis Charles 8 57
- Walpole, Horace 8 57, 9 8, 27, 32
- Ward, James 6 28
- Ward, Thomas 6 25
- Ware, Isaac 8 33
- Warren, David: 'Visit to Chatham Dockyard' 8 52-5i
- Warren, John, talk 9 27
- Waterson, Merlin 3 34, 35
- Weaver, Martin 9 18
- Webb, Mr (of RAC Farnborough) 2 23, 4 36
- Webb, John 4 9
- Webb, Philip 3 26
- Weddel, Philip *see* Grey
- Weimer, Josef 9 64, 65, 66
- Weld family 8 59
- West, Benjamin 6 33, 36
- West, Robert 6 48
- Weston, Mrs 4 17, 29, 30
- Weston, Robert 7 24
- Whatmoge, Barbara, report 2 19-20
- Wheeler, Bert 2 9, 23, 26, 27
- White, Ralph 10 15
- Whitworth, Martin, report 2 20-1
- Wickham, Ann: 'The role of the volunteer' [in the recording of buildings] 7 14-15
- Wilde, Ron 10 13
- Wilkins, William 8 57, 58
- Williams, Gilbert B A 2 3
- Williams, Theo 10 10
- Williamson, John 7 63; report 6 59-60
- Willis, Professor 6 51
- Wilson (*now* Bennett), Corinne 2 42, 43, 44, 7 67; report 2 32-4
- Wilson, Hugh 8 52
- Wilton, Joseph 9 33
- Wiltshire, Kenneth 3 45, 46; 'Sherborne Abbey: work to the North Transept vaulting' 6 51-3i
- Winfield, David 10 14
- Wingate, Michael 8 15; talk 8 56-7; report 7 66-8
- Wood, Edgar 6 18
- Wood, Michael 5 44; 'Darley Abbey, Derby' 5 14-19i
- Wood, R G 4 7, 36; 'Conservation and the architect' 1 3-7
- Wood, Robert 9 43
- Workman, John 9 73
- Wren, Sir Christopher 5 11-14, 8 25-6, 43, 9 8, 11, 12
- Wright, Adela, report 6 58
- Wright, Dr Tom 9 73
- Wyatt, Benjamin 6 27, 36
- Wyatt, Digby 7 66
- Wyatt, James 4 4, 6 41, 43, 9 8, 42
- Wyatt, Samuel 4 4
- Yenn, John 9 42
- Yorke, Philip *see* Hardwicke
- Young, Brian 2 34; reports: Scottish study tour 1976 2 37-9, Shrewsbury 1977 3 36-8, Venice 1978 4 29-30, Wells 1979 4 36-8, Derbyshire 1980 5 38, 41, Bath 1982 7 64

GENERAL INDEX

- Abbees Roding (Essex), Rookwood Hall granary 1 15, f25
- Aberdeen, Triple Kirks 9 46, 59
- Accrington 6 4
- additives, pozzolanic 8 57
- aerial photography 7 29
- Aerofilms 7 29
- aggregates, shrinkage of in concrete 8 48i
- Albano (Italy) 2 21
- alkali-sensitive materials and cement, harmful interaction between 8 48
- Allendorf/Eider (Germany) 9 48, 55
- Allied Brewers 3 39
- Alsfield (Germany) 9 47, 48, 53, 61
- Altenvers (Germany) 9 45, 47, 48, 49, 51
- Amöneburg (Germany) 9 46, 68
- Amsterdam (Netherlands), Dutch gables 8 5i
- Anglia Lead Roofing Co 7 57-8
- Anstrude stone (France) 5 46
- Appuldurcombe (I of W) 10 52
- Apsley House, London 6 31, 36, 10 48
- Archaeology, Institute of Industrial 6 15
- Architectural Association School of Architecture, slide library 7 31
- Architectural Ceramics Society 6 7
- architectural photogrammetric surveys, seminar on standards for 8 59-61
- Architectural Photogrammetry, International Committee for 7 15, 39
- Architectural Photogrammetry Unit, University of York 7 15, 39
- architectural profession and conservation 1 3-7, 2 39-41
- Architectural and Archaeological Photogrammetry Section, National Geographic Institute (France) 7 15
- Architectural Review*, photographic archive 7 33
- architrave 8 49-51i
- archives, photographic 7 27-41 (error noted 8 48)
- Ariccia (Italy) 2 21
- Arkwright Society 5 41
- Ashbourne (Derbys) 5 34, 36-8
- Ashburnham Place (Sx) 4 4
- Ashill brickworks (Nfk) 8 56
- Ashover gritstone 5 15
- Attingham Hall/Park (Salop) 3 34-6, 6 25, 34
- Audley End (Essex) 10 52
- Avon Aqueduct (Wilts) 5 45i
- ballusters, proportions of etc 8 61i
- Barsham (Sfk) 1 42; Rectory 8 18, 19
- Barsham, East *see* East Barsham
- Bath: visits 1975 2 29, 1979 4 39-43, 1982 7 64; Beauford Square 5 47, restoration of Nos 15-20 4 40-1; Bladud, statue of 7 3-5i; Cattle Market 5 47, 6 55; The Circus, No 1 2 29; George V Williams's masonry yard 6 59-60; historic buildings work 4 40; King's Bath 6 23, 55, 7 3i; Lansdown Crescent, No 1 2 29; lime-based mortars, use of in 6 54-6; Marshall Market's House, restoration of 4 42-3; Monmouth Place Priority Area 4 39-40; Pump Room 6 23, 55; Roman Baths 10 3-7i; Roman rendering at the Roman Baths, conservation of 10 3-9i; Royal Crescent, No 1 2 29; Sydney Gardens, bridge over canal 5 30-3i; Trim Street, house in 5 47
- Bath City Council 5 31, 46
- Bath Pictorial*, The, 1895 advertisement 3 47i
- Bath stone 6 59; deterioration of 5 46; freestone 5 48n; imitation of 4 5; mortars for 5 47; use, conservation and repair of 5 45-8i
- Bath Stone Firms Ltd, 1895 advertisement 3 47i
- Bath Technical College 5 47-8
- Bath University 5 47
- Battle Abbey (Sx) 10 52
- Baythorn Hall *see* Birdbrook
- Beccles (Sfk) 8 56
- Bedford Lemere & Co 7 33
- Bedingfield Chantry Chapel 1 41, f55, f56
- Bedingfield estate (Sfk) 8 56
- Bedingham (Nfk), Rookery Farm 8 14i
- Beit, Sir Alfred, Foundation 6 40
- Bellnhausen (Germany) 9 48, 49, 57i
- Bergen (Norway) 9 19, 20i, 10 19i, 20
- Berger Paints 5 22, 7 3
- Berkshire Archaeological Records Committee 7 33
- Bernsfield (Germany) 9 46, 48, 61
- Besace stone (France) 2 42, 4 8, 49
- Betzenrod (Germany) 9 46, 49, 63
- Birdbrook (Essex), Baythorn Hall 1 13, 14, f14, f15, f16/2
- Birmingham: Anglican cathedral 7 11; Bank of England 3 47; Soho House, Handsworth 4 4
- Bischoffen (Germany) 9 57, 58i
- Bisham Abbey Hall (Berks) 1 9
- Bladud, statue of 7 3-5i
- Blake House, Boston (Mass, USA) 1 11
- Blaxter Quarry 7 53
- Blickling Hall (Nfk) 8 3i, 10, 11i, 12, 17
- Blists Hill Open Air Museum 10 59-60
- Bolling Hall, Bradford (Yorks) 6 30
- Bolsover (Derbys) 5 36, 41-2; Castle 8 17, 10 52
- Bolton (Lancs), St Stephen and All Martyrs 6 4
- bonding, Fondedile method 4 13-14, 25i
- borescope 5 8, 7 67, 8 35
- Borley (Essex) 1 15, f26
- Boston (Mass, USA) 1 11
- Box Ground stone 3 47, 5 45, 46, 6 59
- Bowdod (Wilts), Great Drawing Room 10 25-36i
- Brachlian (Bulgaria) 10 22i
- Bracon Ash (Nfk) 1 42
- Bradford (Yorks), Bolling Hall 6 30
- Bradford-on-Avon (Wilts): visit 1975 2 28-9; aqueduct near 5 45i; The Chantry 2 28; Middle Rank, No 4 2 28; Silver Street House 2 28-9
- Braintree (Essex) 1 11, f45, f46
- Brandenburg (Germany): Town Hall 6 3; St Catherine's Church 6 3
- 'brashness' in timber 7 55-6i
- Bredon (Worcs), barn 3 7, 8i, 6 57, 58, 9 19
- Brethane 4 9, 9 3-4, 10 14, 51
- brick: brickwork in Norfolk 8 15-16; damage to 8 46; equivalents for old 8 16; industry in Norfolk 8 55-6; treatment and painting of 2 46-7; perforated 4 47i; repair and replacement 8 16; Roman 8 56

- Bricklayers' Company 8 27  
brickworks *see* Ashill, Cove Bottom  
Brighton (Sx), Royal Pavilion 4 4, 5i, 5 5i, 7 65, 67, 9 17; radiography used at 5 5i  
Bristol: Cathedral 5 46; St Mary Redcliffe Church 3 47; Temple Meads Station, visit 1982 7 65-6  
British Architectural Library 7 30, 31, 33  
bronze staining 8 46  
Broome Park (Nfk) 8 8  
Broughton House (Derbys) 5 42  
Bruges (Belgium): study tour 1977 3 29-33; the Structure Plan 3 29-30; College of Europe Conservation Course 3 29, 32; infill 3 31-2; restoration in Steen Street 3 31  
Bruton (Som) 2 28  
Buckinghamshire: infra-red surveying in cottage 5 5i; lists of historic buildings 10 23-4  
*Building Conservation* 5 2  
*Building of London* (1945), illustration from 5 53  
buildings: recording of, seminar 1982 7 9-17; removal of 5 49, 9 61  
Bulgaria: conservation of timber buildings in 10 21-3i; travels in 7 64-5  
Bungay (Sfk) 8 56  
Bürgeln (Germany) 9 45, 47, 68i  
Burghley House (Northants) 8 6  
Burlington Quarry 7 52, 53-4  
Bury Green (Herts), Clinton's Farm 1 15  
Bury St Edmunds (Sfk) 8 56; Northbury 1 15, f30  
Bush and Wilton Valves Ltd 5 33  
Buxton (Derbys) 6 18, 20
- Caen** stone (France) 3 42, 5 42, 6 47, 8 23, 9 3, 5  
Calp stone (Ireland) 6 47  
Cambridge University Committee of Aerial Photography 7 29  
Canterbury (Kent): Cathedral 7 10, visitor damage 9 7, 9-10; St Augustine's 6 57  
Caprarola (Italy) 2 19  
Carcassonne (France) 7 44-5, 9 20  
Carisbrooke Castle (I o W) 10 50  
carpentry: in the medieval house 1 8-38i; the timber-frame tradition 3 5-28i  
Carrara marble (Italy) 4 31  
Carraraware 6 3  
cast iron: Covent Garden Market, restoration and protection of at 5 24-30; paint removal/cleaning 5 22, 25-7, 6 21-2; new castings 6 21i; Sydney Gardens, Bath, repair of bridge 5 30-1i; and glass verandahs in Southport, restoration and repair of 6 17-23i  
Castletown (Ireland) 6 43-4, 9 43  
Catacluse stone (Cornwall) 1 42  
cathedral glass 7 18  
Cathedrals Advisory Commission for England 7 10-11  
Cathedrals Advisory Committee 7 10  
cathedrals, medieval, interpretation and analysis of 8 21-5i  
Caton (Nfk) 8 56  
cement: indiscriminate use of 5 46; Keene's, and expansion of mortar 8 46-7; Parker's Roman 4 4-5, 8 57; and alkali-sensitive materials 8 48  
Ceramics Society, Architectural 6 7  
Chalfont St Peter (Bucks), Hill Farm 10 24  
Chapel Studio (Herts) 7 65  
Chartres (France), Cathedral 8 22-3i  
Chatham (Kent), Dockyard, visit 1983 8 52-5i  
Chatham Green (Essex), Hyde Hall Cottages 1 11, f44  
Chatham Historic Dockyard Trust 8 55  
Cheddar Palace (Som) 3 5  
Chedgrave (Nfk) 8 19i  
Cheltenham (Glos), visit 1981 7 63-4  
Chesterfield (Derbys), Stud Farm Cottage 5 35  
Chesterford (Essex), Manor House 1 9, 12, f4, f5, f11, f16/1  
Chevington (Sfk), Moat Hall 1 10, f33, f34, f35  
Chicago (USA), Carson Pirie Scott & Co store 6 4  
Chichester (Sx), Cathedral 1 12, 7 11; electronic structural monitoring at 9 11-18i; Works Organisation 2 42  
Chilmark stone 10 14  
Chislehurst (Kent), doorcases from house in 6 27  
Chiswick House (Middx) 9 73, 10 52  
*Church Recorders' Manual* 7 14  
churches: care of 7 9-11; clear glass in 7 17-18; recording of 7 9-11; Sir Edmund Beckett on restoration of 7 6; visitor damage to 9 6-10  
Churches, Council for the Care of 7 9-10, 28  
Cini Foundation 4 32, 33  
City University, Terrestrial Photogrammetry Unit 7 15  
cleaning of stone: in Glasgow 2 35; in Rome 2 17; Temple Church, London 9 3-4i; Vicars' Chapel, Wells 4 7-8; Wells Cathedral 2 4, 7, 4 44  
cleaning of terracotta 6 10-11i  
Clermont Serrard Co 4 49  
clay tiles, plain 2 11-14
- Clinton's Farm (Herts) 1 15  
Clipsham stone 3 42, 5 45, 46, 6 59  
Clumber (Notts) 6 26i, 28  
Cluny (France), Abbey church 8 22  
Coade stone 5 11, 6 3, 4  
Coalbrookdale (Salop) 3 35, 36-7, 5 30, 31; visit 1985 10 57  
Coalbrookdale Company 5 30, 31  
Coggeshall (Essex): Abbey, capella *extra muros* 1 9, f3; Grange Barn 9 25-7i; Paycocke's House 1 13, 15, f22, f23, f28, f29  
Combe Down stone 5 46, 6 58, 59  
Committee of Aerial Photography, University of Cambridge 7 29  
Committee to Rescue Italian Art 4 20  
Compton Place (Sx) 4 4  
computer: -aided drafting in measured drawing 7 25; enhancement of photographs 7 38  
concrete, shrinkage of aggregates in 8 48i  
Conques (France), Abbey church 8 22  
conservation: aerial photography 7 29; architectural profession 1 3-7, 2 39-41; Bath stone in 5 45-6; centres, proposed Scottish 2 39-41; meaning of 1 3-7; photographic archives 7 27-41 (correction 8 48); records 7 10; training, Rome 2 16; X-ray film in 7 39; in Bruges 3 29-33; in France 7 42-7i; in Ireland 6 39-40; in Poland 10 37-47i; in the USSR 9 21-3; of faience 6 3-16i; of glass 7 58-9; of historic landscapes, parks and gardens 9 72-3; of metal sculpture 10 57-9; of monuments 7 61-2; of paint 7 3-5; of Roman rendering 10 3-9i; of stone 7 3-5i; of terracotta 6 3-16i; of tiles 10 60-1; of timber buildings 9 18-21i; of timber buildings in Bulgaria, Japan and Norway 10 16-23i  
Conway Library, Courtauld Institute 7 28, 29, 31-2  
copper staining 8 46  
Core House (Lanarks) 6 27  
corrections: vol 2 *inserted or inside front cover*; vol 4 5 50; vol 5 6 60; vol 9 *insert at 45*  
corrosion: differential aeration 8 45; electro-chemical 8 44-6; stains 8 46  
Corsham (Wilts): Court 6 34; mine 5 45  
Cotswold Treatments Ltd 2 22  
*couchi-couchi/shrucci-cucci/scucci-cucci* method of inserting damp-proof course 4 19, 20, 24, 25i  
Council for the Care of Churches 7 9-10, 28  
*Country Life* 7 29, 32, 33  
county record offices 7 33  
Courtauld Institute of Art 2 9, 10, 7 28, 31, 32  
Courteraie stone (France) 2 42, 43, 5 46, 6 59  
Cove Bottom brickworks (Sfk) 8 56  
Coventry: Cheylesmore 3 8i; Much Park Street 3 14-17i, 20-1i; Spon Street 5 49  
cover meters 5 7i  
Coxwell, Great *see* Great Coxwell  
Cracow (Poland) 10 37, 38i, 44-7i  
cramps/dowels: iron 8 45; metal, detection of in masonry 7 68  
Craven Dunhill & Co 10 60  
Cressing (Essex) 1 8, 9, 11, 13, f40, f41, 9 25-6  
Crest Foundation 4 19  
Cromford (Derbys) 5 40-1  
Crown Estates, photographic archive 7 32  
crown glass in churches 7 17-18  
crucks 2 6-7i, 8  
Culross (Scotland) 2 39  
Cultural Property, International Centre for the Study of the Preservation and Restoration of (Rome) 2 16  
cylinder glass 7 18  
*cyma reversa* architrave 8 49i
- Dale** Abbey (Derbys) 5 15, 17  
damage to churches by visitors 9 6-10  
damp in mud-walled buildings 7 69  
damp-proof courses: indiscriminate use of 5 46; insertion of 4 19, 20; trass 5 11-14, 6 23, 7 18  
Darley Abbey (Derbys) 5 14-19i  
Darley (*in error* Derby) Dale stone 2 39  
Darney Quarry 7 52-3  
David King & Sons 6 19, 21  
Derby 5 34; railway cottages 5 36  
Derbyshire: Archaeological Society 5 15, 17, 18; Historic Buildings Trust 5 34, 35-6, 38, 41; study tour 1980 5 34-44  
deterioration of Bath stone 5 46  
Dietkirchen (Germany) 9 67  
differential transducers/transformers 5 9, 9 13-15i  
Dingley Hall (Northants) 8 7  
Diocesan Advisory Committees 7 9, 41  
Dorchester (Dorset), Roman bath house 7 16  
Dorothea Restoration Engineers Ltd 6 20, 21  
Dorset, visit 8 58-9  
Doulting stone 2 26, 28, 45, 46, 47, 4 8, 43, 7 8  
Doulton 6 4, 10 60  
Dover Castle (Kent) 10 53  
dowels/cramps, iron 8 45  
Drawings Collection, British Architectural Library 7 30
- Dreihausen (Germany), Die Höfe 9 46, 68  
Drogheda (Ireland) 6 45-6  
Droitwich (Worcs), Chorley House 3 7i  
Dublin: study tour 1981 6 37-50i; introduction and postscript to study tour by John Redmill 6 37-8, 50; Bank of Ireland 6 38, 40, 46-7i; Belvedere College 6 42; Casino at Marino 4 3i, 4, 6 31, 49, 9 29-44i; Charlemont House 9 30, 38; Christ Church Cathedral 6 47; Custom House 6 39-40; Dublin Castle 6 50; Gate Theatre 6 42; Henrietta Street 6 43; Hospital Chapel 6 42; Lucan House 6 43; National Concert Hall 6 50; North Great George's Street 6 40-2; Pembroke estate 6 48; Powerscourt House 6 47-8; Rotunda Theatre 6 42; St Stephen's Green 6 48; Trinity College 6 38-9; University Church 6 48  
Dunhouse Quarry 7 52, 53  
Dunmore Pineapple (Scotland), visit 2 38  
Dunsoghly Castle (Ireland) 6 44  
Dutch gables *see* shaped gables  
Dyrham Park (Avon) 6 25i, 26i
- East Anglia**: 16th-c terracotta 1 39-48i; medieval carpentry 1 8-38i  
East Barsham Manor (Nfk) 1 39, 41  
Eastbourne (Sx), Compton Place 4 4  
Eastington Hall (Worcs) 3 6i, 12i  
East Suffolk Building Record 7 33  
Eaton Hall (Cheshire) 6 27  
Edinburgh: visit 1976 2 30-1, 32-4, 35-8; Easter Dalry House 2 35; Holyrood House 2 36; New Town Conservation Committee 2 30, 32-3, 8 32; St Giles Cathedral 7 49; Scott Monument 2 36; sources of lime 7 49; Stenhouse Conservation Centre 2 36-7; Tron Kirk 2 35-6  
electrolytes 8 44-5  
electronic structural monitoring 9 11-18i  
Elmstead Market (Essex) 1 12, 13, f49  
Elterwater Quarry 7 52, 54  
Ely (Cams), Cathedral 8 22i, 9 10, 18; stained glass museum 7 29  
endoscope, fibre-optic 7 67  
English Tourist Board 9 6, 7  
epoxy resin repairs to timber 2 22-3, 8 40-1i  
Ernest Ireland Construction Co 10 15  
Erwarton Hall (Sfk) 8 6i, 7  
Essex County Council, photographic archive 7 33  
ettringite 8 46, 47  
Exeter (Devon), Cathedral 5 50, 7 8  
Excaline 5 47  
expansion of mortar 8 46-8  
exterior treatments to imitate stone 4 3-6
- façades**: replica 2 45-6; retention of 2 46  
Faculty Jurisdiction Commission 7 10  
faience *see* terracotta  
Fanzalo (Italy) 4 27  
Fen Drayton (Cams) 8 20i  
fibreglass, use of 2 46  
fibre-optics: endoscope 7 67; surveying 5 8; use of 8 35  
Fife and St Andrews, visit 1976 2 31-2  
film: intensification 7 38; infra-red and X-ray 5 3-5i, 7 39  
fire, protection of iron against 5 28-30  
floor repairs: Mansion House, London 8 33-43i; Casino at Marino 9 35i  
Florence (Italy): Cathedral 8 4i; S Maria Novella 8 5i  
Fluate stone preservative 3 47, 4 48-9  
fluosilicoisation of stone 4 49  
Fondedile method of bonding 4 13-14, 25i  
Förderkreis alte Kirchen, Marburg (Germany) 9 45, 47-50, 51, 52, 56, 57, 58  
Forest of Dean stone 6 59  
Fornett St Peter (Nfk) 8 16, 17i  
France: conservation in 7 42-7i; stone from 5 46  
Frank Galliers Ltd 3 41  
fresco: to imitate stone and external joinery 4 3-6; at Limburg Cathedral 9 65, 66  
Friedelhausen (Germany) 9 46, 63  
Friedensdorf (Germany) 9 48, 55  
Friends of Terracotta 6 7  
Fritzlar (Germany) 9 46, 53, 70i  
Fulda (Germany) 9 46, 62, 66
- gables**: repair and conservation of 8 13-20i; shaped in Norfolk and Suffolk 8 3-20i  
Gaillon (France), châteaui 1 42, 43  
gamma rays, *see* X-rays  
gardens, parks and landscapes, protection and conservation of 9 72-3  
Gedney House, Salem (Mass, USA) 1 11, 12  
Genzano (Italy) 2 21  
George Jackson & Sons Ltd 10 31  
George King & Sons 7 58  
Geravna (Bulgaria) 10 23  
Gislingham (Sfk) 8 56

- GKN Mills Building Services Ltd 5 21  
 Gladding McBean & Co (USA) 6 4  
 Glasgow: visit 1976 2 34-5; ironfounders 6 19  
 glass: cathedral 7 18; clear, in churches 7 17-18;  
 crown, in churches 7 17-18; cylinder 7 18;  
 stained, repairs to 7 58-9  
 glazing techniques and conservation 7 58-9  
 Gloucester: visit 1978 4 10-14; Blackfriars 4 10-13i;  
 Cathedral precinct 4 14, 8 22; Ladybellegate  
 House 4 13-14  
 Golden Valley (Derbys) 5 34, 36, 41  
 Gopsal Hall (Leics) 6 28, 29i  
 Gosfield (Essex) 1 13  
 Grange, The (Hants) 8 57-8, 59, 10 51  
 granite staining 8 46  
 Grantham (Lincs) 10 61  
 Great Bardfield (Essex), Place House 1 10, f31  
 Great Burstead (Essex) 1 9, f8  
 Great Cornard (Sfk), Abbas Hall 1 9, f6, f7  
 Great Coxwell (Berks), barn 3 7, 8i  
 Great Cressingham (Nfk), Manor/The Priory 1 40,  
 41, 42, f51, f53, f54  
 Greater London Council: Historic Buildings  
 Division 7 28; photographic library 7 33  
 Great Snoring (Nfk), rectory 1 40, 41  
 Gregory Thain 5 45, 47  
 guardianship monuments, management of 10 49-53  
 Godensberg (Germany) 9 47  
 Guiting stone 6 59  
 gunmetal staining 8 46  
 Gunton (Nfk) 7 60-1  
 Gunton's works, Little Plumstead (Essex) 8 56
- Hadrian's Wall** 10 51  
 Halifax (Yorks), All Souls, Haley Hill 7 10  
 Hampton Court (Middx) 9 42, 73; replacement  
 bricks 8 16; terracotta at 6 3  
 Hardwick (Derbys) 5 42  
 Harleston (Nfk) 9 24-5i  
 harling 4 4  
 Hartlepool (Co Durham), Hospital 10 61  
 Hartley Quarry 7 54  
 Hastings (Sx), Holy Trinity Church 3 47  
 Hatfield House (Herts) 8 10  
 Hatherware Ceramics Ltd 6 4, 5i, 6i  
 Hereford: Bishop's Palace 3 5; Cathedral, visitor  
 damage at 9 10  
 Heritage Tile Conservation 10 60-1  
 Herringfleet (Sfk), Manor Farm 8 12i  
 Hessen (Germany) 9 28; listing in 9 61, 69-70; slates  
 and slating in 9 70-1i  
 Hessen, North, and Marburg study tour 1984  
 9 45-71i  
 Hessenpark Open-Air Museum (Germany) 9 46,  
 47, 49, 64  
 Heveningham Hall (Sfk) 9 42  
 Hill Hall (Essex) 10 52  
 hinge, an unusual 10 61i  
 historic buildings: non-destructive surveying of  
 5 3-10i; protection of in Westminster 2 45-7  
 Historic Buildings Section/Division: LCC 5 51-2;  
 GLC 7 28  
 Holkham estate (Nfk) 8 56  
 Hollington Quarry 5 44  
 Holzhausen (Germany) 9 56i  
 Hommertshausen (Germany) 9 49, 56  
 Hongan-ji Temple (Japan) 10 18  
 Hornchurch (Essex), The Chaplaincy 7 24i  
 Horyu-ji Temple (Japan) 9 21, 10 17  
 Houghton Hall (Nfk) 6 27  
 Houghton St Giles (Nfk) 8 16  
 Hoxne (Sfk) 7 58, 8 56  
 Huddleston 3 42  
 Hulton Picture Library 7 33  
 Hyde Hall Cottages (Essex) 1 11, f44  
 hydrological problems of Venice 4 33-4i
- Ilsdorf** (Germany) 9 61i  
 Industrial Archaeology, Institute of 6 15  
 Industrial Monuments Survey of England 7 29  
 infra-red: use of 5 5i; film 7 39  
 Ingenhoff's of Tübingen 7 11  
 Institute of Advanced Architectural Studies,  
 Architectural Photogrammetry Unit 7 15, 39  
 Institute of Industrial Archaeology 6 15  
 insulating material 5 47  
 imitation of stone 4 3-6i  
 interaction: between building materials 8 44-8i;  
 between non-metallic materials 8 46-8  
 International Centre for the Study of the  
 Preservation and Restoration of Cultural  
 Property (Rome) 2 16  
 International Committee for Architectural  
 Photogrammetry 7 15, 39  
 International Council of Monuments and Sites  
 (ICOMOS) 7 15, 9 7, 18, 19, 10 16-23i  
 International Society of Photogrammetry 7 15, 39  
 intumescent mastic 5 28-9i  
 Ipswich (Sfk), Christchurch Mansion 6 26i, 32
- Irish Architectural Library 7 31  
 Irish Georgian Society 6 43, 44  
 Ironbridge (Salop): visits 1977 7 36-8, 1985  
 10 56-61; Blist's Hill Open-Air Museum  
 10 59-60; Coalbrookdale 10 57; Coalport China  
 Works 3 38; Gothick Warehouse 3 37; Heritage  
 Tile Conservation 10 60-1; the Iron Bridge 3 37,  
 repainting and repairs 1980 5 20-3i; Jackfield  
 Tile Museum 10 60; Museum Trust 3 36, 37,  
 5 21; Rose Cottage 3 37; St Mary's Church 10 60  
 Ironbridge Gorge Museum Trust 3 36, 37, 5 21  
 iron staining 8 46  
 ironwork: medieval decorative 6 56-7; protection  
 against fire 5 28-30i; repairs: Covent Garden  
 Market 5 24-30i, the Iron Bridge 5 20-3i, Sydney  
 Gardens, Bath, canal bridge 5 30-33i  
 Ise Grand Shrine (Japan) 9 21, 10 17i  
 Italian Art and Archives Fund 4 20  
 Italian Art, Committee to Rescue 4 20  
 Italia Nostra 2 16
- J K Restorations Ltd** 2 22  
 Jackfield Tile Museum (Salop) 10 60  
 jacking of walls to vertical 5 17i  
 Jackson, George, & Sons Ltd 10 31  
 Japan, conservation of timber structures in 9 21,  
 10 16-18i  
 Japanese Association for the Conservation of  
 Architectural Monuments 10 17  
 jetty construction 3 23i  
 Johannesberg (Germany) 9 46, 47, 61-2
- Kassel** (Germany) 9 44, 53-4  
 Katsura Imperial Detached Palace (Japan) 10 17,  
 18i  
 Keating, J F & Sons Ltd 9 35, 44  
 Kedleston Hall (Derbys) 6 28, 30  
 Keene's cement 8 46  
 Keim paint 8 58, 9 65  
 Kent, tiled roofs in 2 11-14 *passim*  
 Kersey (Sfk): Priory 1 9, f2; River House 8 7  
 Ketton stone 2 43, 3 43, 45, 6 60  
 Killineer House (Ireland) 6 45  
 Kilmainham Hospital (Ireland) 6 49  
 Kilmersdon (Som), Hamilton's: visit 1979 4 39;  
 construction and repair 4 45-7i; mouldings 8 51i  
 Kimberley (Nfk) 8 12  
 King, David & Sons 6 19, 21  
 King, George & Sons 7 58  
 King's Lynn (Nfk), Thoresby College 8 11  
 Kingston Lacy (Dorset) 10 9-15i; visit 9 23-4  
 Kirby Hall (Northants) 8 51, 7i, 8i  
 Kirchberg (Germany) 9 64  
 Kirstead (Nfk), Green Man Inn 8 18i  
 Kiyomizu-Dera Temple (Japan) 10 17, 18i  
 Koprivchitza (Bulgaria) 10 22i  
 Kratzputz 9 56i  
 Kyoto (Japan) 10 17, 18i
- Lacock Abbey** (Wilts) 5 46  
 Lancing College Chapel (Sx) 5 9i  
 Landmark Trust 2 38, 4 42, 5 40  
 landscapes, parks and gardens, protection and  
 conservation of 9 72-3  
 Lane House (Worcs) 3 9i  
 Langenstein (Germany) 9 68  
 Langley Hall (Nfk) 7 62  
 Laon (France), Cathedral 8 23-4i, 9 65  
 laths for tiling 2 13  
 Law, J & A (ironfounders) 6 19  
 Laxfield (Sfk), church 1 13  
 Layer Marney (Essex): tombs in church 1 42, 43;  
 Tower 1 40, f52, 6 3, 8 7i; workshop at 1 43  
 lead: casting 7 57-8; glazing 7 58-9  
 Leeds Fireclay Co 6 4  
 Leicester Castle, Great Hall 3 5  
 Leigh Court (Worcs), barn 6 57, 9 19  
 Lepine stone (France) 4 8, 6 47, 59  
 Leuchars (Fife) 2 32  
 Lichfield (Staffs), Cathedral 6 57  
 Limburg (Germany) 9 46, 47, 64-7i; Cathedral  
 9 64-6, wall-painting 9 65-6  
 lime: historical aspects of use 5 11, 12, 8 56-7;  
 magnesian, and expansion of mortar 8 46-8;  
 mortars for Bath stone 5 47, 6 54-6; plastic  
 repairs at Wells 2 5, 8, 4 44; price of 1672-1711  
 8 25-7; technology 5 46; value of for restoring  
 perished stonework 5 50  
 limestone: damage to sandstone and underfired  
 bricks by 8 46; stains 8 46  
 limewashing stone 3 42, 5 50  
 linear variable differential transformers/  
 transducers 5 9, 7 66, 67, 9 13-15i  
 listing: early history of 10 48-9; in Hessen 9 60, 61,  
 69-70; in Westminster 2 45  
 Little Chesterford *see* Chesterford  
 Little Dunmow (Essex), Priory Place 1 9, 14, f9,  
 f10, f16/4  
 Little Hadham (Herts), Clinton's Farm 1 15
- Little Plumstead (Essex), Gunton's works 8 56  
 Little Stukeley (Cambs), Swan and Salmon Inn  
 8 14  
 Liverpool 6 19  
 local planning authority: drawings for approval  
 3 11, 13; records 7 32-3  
 log for conversion to two studs 3 19i  
 Longford Castle (Wilts) 8 10  
 London: Addison Road, No 8 6 4; Apsley House  
 6 31, 36, 10 48; Baker Street, No 94 2 46;  
 Belgrave Square 2 46; Berkeley Square, No 43  
 2 47; Blew Coat School, Caxton Street 2 47;  
 Boone's Chapel, Lee 7 19i; British Museum 5 50;  
 Buckingham Palace (pre-Webb) 3 47, 4 49,  
 terracotta at 6 4; Camberwell, house in Grove  
 Lane 8 49, 51i; Carlton House 3 35; Chislehurst,  
 house in 6 27; Chiswick House 9 73, 10 52;  
 Chiswick Villa 9 29; Clifton Hill, Nos 15 & 17  
 2 46; Covent Garden Market 5 24-30i, 8 60;  
 Cumberland House, Pall Mall 10 34; Dean  
 Street, No 75 10 48; Derby House, Grosvenor  
 Square 6 28i; Devonshire Place, Nos 3-5 2 46;  
 Dulwich College 6 4; Dulwich Picture Gallery  
 6 33-6i; Empire Theatre, Hackney 6 4; Fournier  
 Street, No 14 7 20i; Geffrye Museum 10 48;  
 Gloucester Place, Nos 24-40 2 46; Gower House,  
 Whitehall 6 26i, 27; Guildhall 4 4; Ham House  
 8 43; Hammersmith, garden building for Lord  
 Melcombe 6 28; Hampton Court 8 16, 9 42, 73;  
 Harrods 7 25i, 10 60, 61; Holland House 8 10;  
 Hornchurch, The Chaplaincy 7 24i; Hotel  
 Russell, Russell Square 6 4; House of Lords  
 6 34, 7 55-6i; Houses of Parliament *see* Palace  
 of Westminster; Huxley Building, Exhibition  
 Road 6 4; Kew Gardens, Dutch House 8 8;  
 Kenwood House 6 29; King's Gate, Whitehall  
 8 7; Lambeth Palace 5 13; Little Plumstead,  
 Gunton's works 8 56; Liverpool Street Station  
 8 56; Lloyd's, Bowdoin Great Dining Room  
 10 25-36i; Mansion House 8 33-43i, 60; Michelin  
 Tyre Co, Fulham Road 6 4; Mortimer House,  
 Egerton Gardens 7 21i; Natural History Museum  
 6 8; Onslow Gardens, No 23 7 22i; Osterley Park  
 4, 4, 6 26i, 28, 31, 9 42, 10 35; Oxford Market,  
 Oxford Street 10 2i; Palace of Westminster 4 48,  
 5 50, 6 34, 7 55-6i; Pelham Crescent 7 23i;  
 Pembroke House, Whitehall 9 42; Piccadilly, No  
 63 2 45; Pitzhanger Manor, Ealing 6 26i, 29, 34;  
 Playhouse Theatre, Westminster 7 26i;  
 Prudential Insurance Co, High Holborn 6 4;  
 Queen Mary's Hospital, Roehampton 5 52;  
 Regent Street, No 14 5 13; Regent's Park, houses  
 4 4, 5; Regent Square Presbyterian Church  
 10 48; Royal Albert Hall 6 4; Royal College of  
 Science 6 4; St George Hanover Square 10 48;  
 St James's Palace 6 28, 29i; St James's Square,  
 No 15 6 27, No 20 6 29; St Katherine Cree 7 65;  
 St Lawrence's Church, Morden 7 65;  
 St Lawrence's Church, Whitechurch 7 11i;  
 St Margaret's Church, Edware 7 65; St Martin-  
 in-the-Fields 3 47, 4 49; St Pancras Station, visit  
 6 60; St Paul's Cathedral 3 47, 4 49, electronic  
 structural monitoring at 5 9, 9 11-18i,  
 photogrammetry at 7 06, price of lime in its  
 rebuilding 8 25-7, use of trass at 5 11-14, visitor  
 damage 9 7; St Thomas's Square, No 1,  
 Hackney 7 20i; Sicilian Avenue 6 4; Somerset  
 House 4 4, 6 27i, 30, 9 44; South Audley Street,  
 No 71 2 47; Stratford Town Hall 7 7i;  
 Strawberry Hill, talk 9 27; Syon House 10 35;  
 Temple Church 9 3-6i; Tower of London 1 12,  
 5 50, 7 8, 10 50; Trinity Chapel, Mile End Road  
 5 52; Trinity Hospital, Mile End Road 7 23;  
 Victoria and Albert Museum 6 4, 34; Vine  
 House, Kingston 8 50, 51i; Westminster,  
 protection of historic buildings in 2 45-7;  
 Westminster Abbey 3 47, 4 49, 7 8, visits 1978  
 3 42-3, 1981 7 58-9, Chapter House 10 50,  
 mortar 3 42-3, photogrammetry in cloister 7 16,  
 whitewashed 5 50; Westminster Hall  
 whitewashed 5 50; York Watergate 10 48  
 London County Council Historic Buildings Section  
 5 51-2  
 'London Needs a New Plan Now', illustration from  
*The Building of London* (1945) 5 53  
 London Survey Committee 7 23, 10 48  
 Long, J & Sons (Bath) Ltd 5 33  
 Lucan House (Ireland), visit 6 43  
 Luddesdowne (Kent), church 6 26i, 28  
 Lulworth (Dorset): Castle 8 58-9, 10 52; Chapel  
 8 59
- McAlpine**, Sir Robert 4 14  
 magnetometry 5 7-8i  
 Maiden Castle (Dorset) 10 52, 53  
 Malcontenta (Italy), Villa Foscari 4 25, 26  
 Mallinson's Wood Products Ltd 9 35  
 Manchester, Holy Trinity Church, Platt Lane 6 4  
 Mannington Hall (Nfk) 1 40

INDEX TO VOLUMES 1-10

- marble *see* Carrara, Purbeck  
Mansfield, Red, stone 6 60  
Marburg and North Hessen (Germany): study tour 1984 9 45-71i; Förderkreis alte Kirchen 9 45, 47-50, 51, 52, 56, 57, 58  
Margaretting (Essex) 1 13  
Marino (Ireland), Casino 4 3i, 4, 6 31, 49, 9 29-44i  
Martock (Som): visit 1975 2 22-3; All Saints Church, nave roof 2 24-5i  
Maser (Italy), Villa Barbaro 4 28-9  
masonry, detection of cramps/dowels in 7 68  
mastic: intumescence 5 28-9i; medieval, in stone repairs 7 7, 8  
materials: harmful interactions between 8 44-8i; non-destructive methods of testing 7 66-8  
Maw & Co 10 60  
Meadwell/Medwell Quarry 5 48n, 6 59  
measured drawing: tradition of in *The Survey of London* 7 19-26i; use of computer-aided drafting 7 25; use of photogrammetry 7 25; use of photographic montage techniques 7 22; use of process cameras 7 24-5; at Vicars' Close, etc, Wells 4 9  
measurement: of moisture 7 68; of movement in buildings 5 8-10, 7 66-7, 9 11-18i  
Mechelen (Belgium), Palais de Savoie 8 4, 5  
medieval: carpentry 1 8-38i; cathedrals, interpretation and analysis of 8 21-5i; decorative ironwork 6 56-7; stone repair 7 7-8i  
Melhuish & Saunders Ltd 4 9  
metal sculpture, conservation of 10 57-9  
metals: corrosion 8 44-6; victim and aggressor metals, and harmful interactions between 8 44-5  
Michelmersh Brick Co 8 58  
microscopy in examination of paint samples 6 29-30  
microwave analysis 5 6-7i  
Middle Littleton (Worcs), barn 3 19i, 6 57, 9 19  
Milan (Italy), S Maria della Grazie 6 3  
Modern Floors Ltd 9 35  
moisture measurement 7 68  
monitoring structural movement 5 8-10i, 7 66-7, 9 11-18i  
Monk's Park stone 5 45-6, 6 55, 59; 1895 advertisement 3 47  
Monkton Farleigh mine 5 45  
Montacute House (Som) 8 11  
montage techniques, use of in measured drawings 7 22  
Montford (Salop), barn 3 41  
'monument', meaning of 9 28  
Monuments and Sites, International Council of 7 15, 10 16-23  
monuments, conservation of 7 61-2  
Monument Trust 5 38  
Moor Park (Middx) 8 37  
mortar: for Bath stone 5 47; expansion 8 46-8; development in Scotland 7 47-51i; Westminster Abbey 3 42-3  
Moscow (USSR), St Basil's Cathedral 9 22i, 23  
mouldings 8 49-51i  
movement in buildings, measurement of 5 8-10i, 7 66-7, 9 11-18i  
Much Wenlock (Salop), visit 3 38  
mud-walled buildings and damp 7 69  
Mulbarton Green (Nfk), Old Hall 8 15  
Murano (Italy) 4 16-17i  
Murhill Quarry 5 48n
- Nara period (Japan) 10 17**  
National Association of Decorative and Fine Arts Societies 7 14-15, 9 6  
National Geographic Institute (France) 7 15, 39  
National Monuments (*formerly* Buildings) Record 4 42, 7 11-13, 27-30  
National Monuments Record (Scotland) 7 30-1  
National Monuments Record (Wales) 7 31  
National Trust 4 42, 6 58, 9 19, 23, 10 9, 15; photographic collection 7 32  
National Trust (An Taisce) Archive, Dublin (*now* Irish Architectural Library) 7 31  
National Trust for Scotland 2 30, 31, 32, 38, 39  
Nemi (Italy) 2 21  
Nessebur (Bulgaria) 10 21, 22i, 23  
Netherlands: shaped gables in 8 4-6; influence on England 8 7-8  
Newby Hall (Yorks) 9 42  
New England plan 3 9i  
Newgrange (Ireland), visit 6 45i  
Newport (Essex), Crown House 1 10, f36  
Newson, W H, catalogue 8 49i  
New York City (USA), Woolworth Building 6 4  
Nieborów (Poland) 10 47i  
Niederbühl (Germany) 9 48  
Niedereisenhausen (Germany) 9 46, 49, 55i, 56i  
Niederweimar (Germany), visit 9 51, 52i  
Nikko (Japan) 10 17  
Ninfa (Italy) 2 21  
non-destructive: methods of testing 7 66-8; surveying techniques 5 3-10i  
non-metallic materials: harmful interactions between 8 46-8; stains 8 4-6  
Nonsuch (Surrey) 8 6  
Norfolk: brick industry 8 55-6; shaped gables 8 3-20i  
Norman & Underwood 2 26-7  
Northbury, Bury St Edmunds (Sfk) 1 15, f30  
Northern England, quarrying in 7 52-4  
North Hessen *see* Hessen  
Norway, conservation of timber buildings in 10 18-21i  
Norwich 8 56; study tour 1982 7 56-62; Bacon House 7 60; Bracondale Manor 8 10, 19; Cathedral 8 23-4i; churches 7 62; The Close, No 6 8 15i, 16, 18, 20; Cow Tower 8 56; The Old Barge 7 59-60i; The Red Lion, Eaton 8 16i; Thorpe station 8 56; tombs 1 41, 42, 43  
Norwich Survey Group 8 5, 14  
Nostell Priory (Yorks) 6 25i  
Nottingham, Severn's 3 6i  
numerals, assembly, on timber frames 3 18i
- oak, stains 8 46**  
orthophotography 7 39  
Osborne House (1 o W) 10 61  
Osterley Park (Middx) 4 4, 6 26i, 28, 31, 9 42, 10 35  
Over (Cambs) 8 12i  
Oxborough/Oxburgh (Nfk): Hall 8 56; tombs in church 1 41, 42, 43, f55, f56  
Oxford 8 45, 56; New College 7 58; Tom Tower 6 3
- paint: conservation 7 3-5; on brick and stucco 2 47; removal of from cast iron 5 22, 25-7, 6 21; removal of from stone 5 47; repainting 18th-c interiors 6 25-32i; samples at the Casino, Marino 9 36i; samples, examination of by microscopy 4 3i, 6 29-30; stripper 5 47; system for the Iron Bridge 5 22**  
Palladian villas in the Veneto, visit 4 25-9  
Palmyra, Temple of the Sun 9 43  
Paris, Abbey church of St Denis 8 23  
Parker's Roman cement 4 4-5, 8 57  
parks, gardens and landscapes, protection and conservation of 9 72-3  
Pattiswick (Essex), church 1 15, f21  
Pavia (Italy), Certosa 6 3  
Pennant stone 6 59  
Peterborough (Northants), Cathedral, visitor damage 9 10  
Petworth Park (Sx) 6 34  
Peyrou stone (France) 6 58  
Phillips & Page 9 8  
philosophy of repair 5 47; historical authenticity 2 4-5  
photogrammetry 7 13, 15-16, 38-9; standards for surveys 8 59-61; use of in measured drawings 7 25; International Committee for Architectural 7 15, 39; International Society of 7 15, 39; Unit, City University 7 15; Unit, University of York 7 15, 39  
photographic archives: care of 7 36-8; role of in conservation 7 27-41 (correction 8 48); using old photographs 7 34-6  
photography: aerial 7 29; computer enhancement 7 38; high contrast copying 7 38; montage techniques for measured drawings 7 22; rectified 7 39; stereo 8 28-32i; use in restoration of west front of Wells Cathedral 7 34  
Pilgrim Trust 2 23, 27  
pins for tiling 2 12  
Pitzhanger Manor, Ealing 6 26i, 29, 34  
plain-tiled roofs, late 17th-c and early 18th-c practice 2 11-14  
Poland, conservation in 10 37-47i  
Portland cement and sulphate solutions, harmful interactions between 8 46-7  
Portland stone 2 42, 3 42, 4 49, 6 49, 58, 59, 8 58, 9 11, 34; Whitbed 5 46  
pozzolana 5 11, 13, 47; additives 8 57  
preservation: historic buildings in Derbyshire 5 34-5; timber-framed buildings 3 5-28i  
preservation orders 10 49  
preservatives: Fluote 3 47, 4 48-9; Santobrite 4 49; wine & shellac 3 42  
process camera, use of in measured drawings 7 24-5  
Pro Venezia Viva, work of 4 21-2  
public inquiries 2 45, 46  
pulse radar 5 6-7  
Purbeck marble 4 36, 8 58  
Pynfords 2 44, 4 24, 5 44
- Quarr stone 2 43**  
quarries: Northern England study tours 1981, 1982 7 52-4; in Scotland 7 52; ultrasonic surveying 5 5-6; *see also* Blaxter, Burlington, Corsham, Darney, Dunhouse, Elterwater, Hartley, Hollington, Monkton Farleigh, Meadwell, Murhill, St Aldhelm's, Springwell, Stainton, Wellfield, Woodkirk
- Rachelshausen (Germany) 9 57**  
radio-detection surveying 8 35  
radiography 5 3-5i  
Radio-televisione Italiano 4 30  
*Radio Times*, photographic archives 7 33  
Radwinter (Essex), Old Forge 1 f27  
Rathbeale Hall (Ireland) 9 44  
Rattee & Kett 3 43  
Rauischholzhausen (Germany) 9 68  
Raynham Hall (Nfk) 8 8, 11  
recording: architectural 7 13-14; buildings, seminar 1982 7 9-17; churches 7 9-11; role of the volunteer 7 14-15  
rectified photography 7 39  
Redbank Manufacturing Co 6 4  
Redundant Churches Fund 7 34  
Reedham (Nfk) 8 56; church 7 62  
Reepham (Nfk) 1 12, f47, f48  
Reichenbach (Germany) 9 46, 54-5  
Reigate stone 3 42  
Reims (France) 8 22  
re-leading glass windows 7 18  
removal of buildings 5 49, 9 61  
rendering, conservation of Roman at Bath 10 3-9i  
Renofors 2 43, 8 37  
repair of stone 2 5, 8, 4 7-9, 5 46-7, 7 7-8i  
repair, philosophy of 5 47-8  
repairs notices 2 45  
replica façades 2 45-6  
Report of Committee on decay of stone of New Palace at Westminster 1861 4 48  
reports of ASCHB events *see* seminars, study tours, talks, visits  
resins: Sikadur 8 40; epoxy repairs to timber 2 22-3, 8 40-1i  
restoration: meaning of 1 3-7; of churches 7 6  
Rickmansworth (Middx), Moor Park 8 37  
Roman: bricks 8 56; rendering at Bath, conservation of 10 3-9i  
Roman cement, Parker's 4 4-5, 8 57  
Rome: study tour 1975 2 15-21; St Peter's (Constantine's church) 8 23i  
roofs: carpentry 1 8-38i; tiled, in Kent 2 11-14  
*passim*; tiled, post-Great Fire and early 18th-c practice 2 11-14  
Rookwood Hall (Essex) 1 15, f25  
Röros (Norway) 10 20-1i  
Royal Commission on Historical Monuments for England 7 11-13, 28-30  
Royal Institute of British Architects 7 30, 31, 33; Drawings Collection 7 30  
Ruabon 6 4  
Runton, West *see* West Runton  
Russborough House (Ireland) 6 40
- Saffron Walden (Essex), church 1 13**  
St Albans (Herts): Roman bricks 8 56; Abbey whitewashed 5 50  
St Aldhelm's Quarry (Dorset), visit 8 58  
St Andrews and Fife, visit 1976 2 31-2  
St Clere's Hall (Essex) 1 14-15, f19, f20  
St Denis (France) 8 23  
St Maximin stone (France) 5 46, 6 47  
St Papoul (France) 7 44  
St Wandrille (France), Abbey 9 20, 21  
Salem (Mass, USA) 1 11, 12, 13  
Salisbury (Wilts): visit 1978 3 44-6; Bishop's Palace etc 3 45-6; Cathedral 5 44-5; visitor-damage to 9 10, whitewashed 5 50  
Saltram House (Devon) 6 31, 34, 10 34  
salts forming electrolytes 8 44  
sanding to imitate stone 4 3-4  
sandstones, damage to by limestone 8 46  
Sandviken (Norway) 10 20  
Santobrite, stone preservative 4 49  
sash windows: origin of 8 43; transom detail 4 46i  
Save Venice Inc 4 30, 34  
Sawtry (Cambs), Manor Farm 8 19  
Schotten (Germany) 9 62-3  
scissor scarf 3 19i  
Scole (Nfk), White Hart Inn 8 12, 19i  
Scotland: Scottish study tour 1976 2 30-41; mortars in 7 47-51i (comment 8 32); proposed conservation centres 2 39-41  
*scucci-cucci see couchi-couchi*  
Selton Metropolitan Borough Council 6 19  
Selby (Yorks) 8 21, 22i  
seminars, ASCHB, reports of: Bath stone in building, 1980 5 45-8i; recording of buildings, 1982 7 9-17; standards for photogrammetric surveys, 1984 8 59-61; Sermoneta (Italy) 2 21  
shaped gables: in Norfolk and Suffolk 8 3-20i; origin of 8 3-8i; repair and conservation of 8 13-20i; survey of 8 8-13i  
Shardlow (Derbys) 5 34, 42-3

- Shaws of Darwen 6 4  
 shelter coats 2 8, 9  
 Sherborne (Dorset), Abbey 6 51-3i  
 Shrewsbury: study tour 1977 3 34-4i; Castle Gates Library & Riggs Hall 3 39-40; early photographs 3 36  
 Shrubland Old Hall (Sfk) 1 40  
 Shugborough (Staffs) 4 4  
 Sikadur resins 8 40  
 silane/silicone treatment 2 5, 7-8, 3 45, 4 9, 30-1, 5 47; A warning and a plea 4 48  
 Silberg (Germany) 9 49, 56  
 Silverston 7 8  
 slate: Burlington Quarry 7 53; fish-scale 4 47i; in Hessen 9 70-1i  
 sliding (sash) windows 8 43  
 Society for the Protection of Ancient Buildings 3 10, 5 50, 6 54, 7 34; reply to F W B Charles 5 49; 'Silanes: A warning and a plea' 4 48  
 Somerleyton (Sfk) 8 56  
 Southport (Lancs), restoration of verandahs in 6 17-23i  
 South Wingfield Manor (Derbys) 5 42  
 Sozopol (Bulgaria) 10 21  
 Springwell Quarry 7 52, 53  
 Sprowston (Nfk) 8 56  
 Stabilometer 9 15-16i  
 stained glass, conservation of 7 58-9, 65  
 staining, copper, metal, steel 8 46  
 stains: corrosion 8 46; non-metallic materials 8 46  
 Stainton Quarry 7 52, 53  
 Stansells (of Taunton) 2 27  
 steel staining 8 46  
 Stenhouse Conservation Centre 2 36-7, 40  
 stereo viewing 8 28-32i  
 Steventon (Berks) 1 12  
 Stirling Castle (Scotland), visit 2 38-9  
 Stisted (Essex), Bay Tree Farmhouse 1 11, f42  
 stone: cleaning *qv*; conservation 5 50, 7 3-5; deterioration 4 46, 5 46; French 3 42, 5 46, 6 59; jointing 5 46; preservation 3 42, 47, 4 48-9, 5 50; repair 2 5-6, 8, 4 7-9, 5 46-7, 7 13, medieval 7 7-8i; types see Anstrude, Ashover, Barnack, Bath, Besace, Box Ground, Caen, Calp, Carrara, Catacluse, Chilmark, Clipsham, Coade, Combe Down, Courteraie, Darley, Doulting, Forest of Dean, Guiting, Haute Roche, Huddleston, Ketton, Lepine, Mansfield Red, Monk's Park, Pennant, Peyrou, Portland, Purbeck, Quarr, Reigate, St Maximin, Taynton, Trochert, Verona, Weldon, Westwood, York  
 Stonehenge (Wilts) 10 50, 53  
 Stothert & Pitt Ltd 5 31, 33  
 Stott Park Bobbin Mill (Cumbria) 10 51  
 Stourhead, trass at 7 18  
 Stowmarket (Sfk), Abbot's Hall 8 56  
 Strawberry Hill (Middx), talk 9 27  
 Stuarts Granolithic Co Ltd 4 9  
 Studley Royal (Yorks) 4 4  
 study tours and longer visits by ASCHB, reports of: Bruges 1977 3 29-33; Derbyshire 1980 5 36-44; Dublin 1981 6 38-50i; Edinburgh 1976 2 30-31, 32-4, 35-8; Ironbridge 1985 10 56-61; Marburg and North Hessen 1984 9 45-71i; Martock, Wells, Bradford-on-Avon & Bath 1975 2 22-29i; Northern England quarrying 1981, 1982 7 52-54; Norwich 1982 7 56-62; Rome 1975 2 15-21; Scottish 1976 2 30-41; Shrewsbury 1977 3 34-41; Venice 1978 4 16-34i; Wells & Bath 1979 4 35-43i; see also visits  
 Stutton Hall (Sfk) 8 7  
 Suffolk, shaped gables in 8 3-20i  
 Suffolk County Council, photographic archive 7 33  
 sulphate solutions and Portland cement, harmful interaction between 8 46-7  
 sulphuric acid staining 8 46  
 Surrey County Council, photographic archive 7 33  
 Survey of London 5 51, 7 19-26i, 10 48, 50  
 survey: techniques, non-destructive 5 3-10i; of timber-framed buildings 3 10-11, 13-18  
 Sutton Place (Surrey) 1 39, 40, 41, 6 3  
 Sutton Scarsdale Hall (Derbys) 5 42  
 Swakeleys (Middx) 8 8  
 Syon House (Middx) 10 35  
 talks, ASCHB, reports of: brick industry in Norfolk, 1983 8 55-6; conservation in USSR, 1984 9 21-3; conservation of monuments, 1982 7 61-2; Grange Barn, Coggeshall, 1984 9 25-7i; hydrological problems of Venice, 1978 4 33-4; historical aspects of the use of lime, 1983 8 56-7; medieval decorative ironwork, 1981 6 56-7; non-destructive testing of materials, 1982 8 66-8; problems of restoring Venetian buildings, 1978 4 23-5i; repair of historic timber structures, 1977 3 38; Strawberry Hill, 1984 9 27; structural stability of walls, 1976 2 37-8; travels in Bulgaria, 1982 7 64-5  
 Tamworth Castle (Staffs) 6 27, 31  
 Taynton stone 3 42, 6 58  
 Telford New Town (Salop) 3 36  
 tell-tales 5 8-9; 7 66-7  
 Terracotta, Friends of 6 7  
 terracotta (and faience): cleaning 6 10-11i; conservation 6 3-16i; deterioration 6 7-9i; in East Anglia, 16th-c 1 39-48i; history 6 3-4; manufacturing process 6 4-6i; maintenance etc 6 12-15; producers 6 4i; soiling 6 9-10i; tombs 1 39, 41-43, f55, f56  
 Tharston (Nfk) 8 17  
 Thaxted (Essex), Tinkers Green Farmhouse 1 11, f43  
 theodolites 7 67  
 Tighe, J D & Co (Midland) Ltd 5 22  
 tiles: conservation of decorative 10 60-1; hand-made plain clay 2 11-14; mathematical 3 46  
 timber: 'brashness' 7 55-6i; conversion 3 18-19i; plastic repair 2 22-3; repair schedules 3 19, 22i  
 timber buildings, conservation of 3 5-28, 38, 9 18-21i; in Bulgaria 10 21-3i; in Japan 10 16-18i; in Norway 10 18-21i  
 timber-frame tradition 3 5-28i (comments by SPAB & footnote by F W B Charles 5 49)  
 Timber Research and Development Association 9 35  
 Tinkers Green Farmhouse (Essex) 1 11, f43  
 Tintagel (Cornwall) 10 52, 53  
 Tintern Abbey (Gwent) 9 71  
 Tiptofts (Essex) 1 14, f12, f13, f16/3  
 Todai-ji Temple (Japan) 9 21i  
 Toddington (Beds), Sir Henry Cheney's house at 8 8, 10  
 tombs, terracotta 1 39, 41-3, f55, f56  
 Toothill (Essex), Doe's Farmhouse 1 10, f37, f38  
 Torcello (Italy), visit 4 17-18  
 Toruń (Poland) 10 43-4i  
 Totternhoe (Beds) 8 57  
 Toulouse (France) 7 42-4i, 45i, 46i  
 transducers/transmitters 5 9i, 10i, 9 13-15i  
 trass: use of in Wren period 5 11-14, 6 23; reference in *Gwilt* 6 23; at Stourhead 7 18  
 Trerice (Cornwall) 8 7i  
 Treysa (Germany) 9 46, 47, 52-3  
 Triavna (Bulgaria) 10 21, 22i, 23  
 Trochert stone (Germany) 9 65  
 Tronçais, Forest of (France) 9 19i  
 Trondheim (Norway) 10 20  
 Twyford (Derbys) 5 36  
 Tyne and Wear County Council, photographic archive 7 33  
 Ulting (Essex), Raven's Farmhouse 1 10, 13, f32  
 ultrasonics 5 5-6i  
 Uppark (Sx) 6 25, 9 73  
 Urnes (Norway), stave church 9 20i, 10 19i, 21, 23  
 USSR, conservation in 9 21-3i  
 Vale Royal 7 8  
 Varley, John & Sons 6 20  
 Veneto, Palladian villas, visit 4 25-9  
 Venice (Italy): study tour 1978 4 15-34i; basilica of SS Maria e Donato, Murano 4 17i; basilica of St Mark 1 4; chimneys 4 23i; church of S Maria Assunta dei Gesuiti 4 29i; church of S Giorgio Maggiore 4 32-3; church of S Nicolo dei Mendicoli 4 18-19i; church of the Pietà 4 19-20; foundation 4 24; Ghetto 4 29; Grand Canal 4 16; Greek Orthodox Synagogue 4 29-30; hydrological problems 4 33-4i; Mestre 4 15; Palazzo Fortuny 4 23i; Palazzo Labia 4 30; Porta della Carta 4 30-1; problems of restoring its buildings 4 23-5i; Pro Venezia Viva 4 21-2; research on pollution 4 22-3i; role of private committees in restoration 4 19-21; Save Venice Inc 4 30, 34; Scuola di S Pasquale 4 21-2; Spanish Synagogue 4 30; Venice in Peril Fund 4 18, 22, 34  
 verandahs, Southport, restoration and repair of 6 17-23i  
 Verona stone (Italy) 4 31  
 Versailles (France) 9 29  
 Vézelay (France), Cathedral 9 20  
 Vienna (Austria), Bundesdenkmalamt 7 15  
 Villa Barbara (Italy) 4 28-9  
 Villa Emo (Italy) 4 27  
 Villa Foscari (Italy) 4 25-6  
 VISAR conference 1984 8 28-32i  
 visitor damage to churches 9 6-10  
 visits by ASCHB, reports of: Attingham Hall (Salop) 1977 3 34-6; Bath 1982 7 64; Chapel Studio (Herts) 1982 7 65; Chatham Dockyard 1983 8 52-5i; Cheltenham 1981 7 63-4; Dorset 1983 8 58-9; Dunmore Pineapple 1976 2 38; Fife and St Andrews 1976 2 31-2; Glasgow 1976 2 34-4; George V Williams' Masonry Yard, Bath 1981 6 59-60; Gloucester 1978 4 10-14i; The Grange (Hants) 1983 8 57-8; Gunton Park (Nfk) 1982 7 60-1; Hamilton's, Kilmersdon (Som) 1979 4 39; Harleston (Nfk) 1984 9 24-5; Ironbridge 1977 3 36-8; Kingston Lacy (Dorset) 1984 9 23-4; Lulworth Castle (Dorset) 1983 8 58-9; Montford barn (Salop) 1977 3 41; Much Wenlock (Salop) 1977 3 38; St Aldhelm's Quarry (Dorset) 1983 8 58; Palladian Villas in the Veneto 1978 4 25-9; St Pancras Station 1981 6 60; Salisbury 1978 3 44-6; Stirling Castle 1976 2 38-9; Temple Meads Station, Bristol 1982 7 65-6; Wells Cathedral, excavations at 1979 4 36; Westminster Abbey 1978 3 42-3, 1981 6 8-9; Winchester 1976 2 42-4; Worcestershire barns 1981 6 57-8; Wrest Park (Beds) 1985 10 54-6i; see also study tours  
 Viterbo (Italy) 2 19  
 Volpertshausen (Germany) 9 46, 47, 49, 64  
 Vös (Norway), doorway 10 20i  
 walls, structural stability of 2 37-8  
 Walmer (Kent) 6 31, 32, 10 52  
 Walter Macfarlane (ironfounders) 6 19  
 Warsaw (Poland) 10 39i, 40, 41-3i  
 waterproofing, trass as a means of 5 11-14, 6 23, 7 18  
 Wattsfield (Sfk) 8 56  
 weathering 3 25i  
 Weidenhausen (Germany) 9 47, 58, (*in error* Weylinghausen) 64  
 Weilburg (Germany) 9 46, 67  
 Weldon stone 2 42  
 Wellfield Quarry 7 54  
 Wells (Som): visits 1975 2 23, 26-28, 1979 4 35-9; Bishop's Palace 2 27, 4 38-9; St Cuthbert's Church 2 27-8; Vicars' Close/Chapel/Hall 2 26, 4 7-9, 36-9, 7 16  
 Wells Cathedral 2 23, 26-7, 4 35-6, 5 47, 50, 7 10-11, 41; Bishop Bekynton's tomb 6 57; excavations at 4 36; library 2 26-7; medieval repairs 7 7-8i; photogrammetry 7 16, 8 60; photographs 2 9-10, 7 34, 8 60; West Front conservation 2 3-10, 4 43-4; West Front records 2 9-10  
 West Dean College (Sx) 9 72-3  
 Westerfield Hall (Sfk) 8 15  
 West Runton (Nfk) 8 56  
 Westwood stone 5 45i, 6 55, 59  
 Wethersfield (Sfk), church 1 12  
 Weylinghausen see Weidenhausen  
 White Roding (Essex), church 1 9, 12  
 whitewash 5 50  
 Williams, G V & Sons, masonry yard, visit 6 59-60  
 Wimbish (Essex), Tiptofts 1 14, f12, f13, f16/3  
 Winchester (Hants): visit 1976 2 42-4; Cathedral 2 42-4, visitor damage 9 10; The Close 2 42; College 7 58; Hyde House 8 17; Old Minster 8 21i  
 windows: sash 8 43; terracotta 1 39, 40  
 Windsor (Berks): Castle 1 8, f1; St George's Chapel 6 56, 9 7, visitor damage 9 10  
 Wingfield Castle 8 56  
 Wirksworth (Derbys) 5 34, 35, 36, 38-40  
 Witley Court (Worcs) 10 51  
 Witnessham Hall (Sfk) 8 7  
 Witt Collection, Courtauld Institute 7 31, 32  
 Wolford Green (Nfk) 8 18i  
 Wollaton Hall (Notts) 8 5  
 Wommelshausen (Germany) 9 49, 57  
 Woodkirk Quarry 7 54  
 Worcester, Guesten Hall 9 20i  
 Worcestershire barns, visit 1981 6 57-8  
 Wrekin Construction Ltd 5 21  
 Wrest Park (Beds) 10 52, 54-6i  
 wychert 5 5i  
 Wymondham (Nfk): tomb in church 1 42; Sun Inn 8 15  
 X-rays and gamma rays 5 3-5i, 7 39, 67  
 York: Minster 9 18; section through paint layers of unidentified house 4 3; stone 6 59  
 York University, Institute of Advanced Architectural Studies 7 15, 39